

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0837/2020/NS
DATE : 3-Nov-20
WIP : 56404

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN KIAN CHYE
ADDRESS : 65 PORTCHESTER AVENUE
SINGAPORE 556347
TELEPHONE : HP +65 96699292
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100494350-03
VEHICLE NO : **SLJ 5881 X**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 16/12/2016
ENGINE NO : CVN 028124
CHASSIS NO : WAUZZZF46HA091628
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Nov-20
PLACE OF ACCIDENT : 100 LORONG KISMIS S598031



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 5881 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250.
3	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N \$ 350.00	X. 280.
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X.
SUB TOTAL LABOUR CHARGES		: \$ <u>2,180.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 5881 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	✓ 1000
6	TO RESPRY FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 3,600.00	✓ 1650
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,452.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 5881 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONTBUMPER <i>Distorted</i>		\$ 2,111.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 282.00	x
3 FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 70.00	?
4 FRONT BUMPER GRILLE - CENTRE <i>new</i>		\$ 194.00	x
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$ 208.00	x
6 FRONT BUMPER AIR GUIDE - LH <i>new</i>		\$ 62.00	x
7 RADIATOR GRILLE <i>new</i>		\$ 1,139.00	x
8 FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>		\$ 134.00	+
9 FRONT BUMPER CARRIER <i>?</i>		\$ 795.00	+
10 FRONT BUMPER FOAM FILLER PIECE <i>new</i>		\$ 123.00	x
11 FRONT BUMPER TOP COVER <i>?</i>		\$ 126.00	x
12 FRONT BUMPER GUIDE SECTION - LH <i>?</i>		\$ 36.00	?
13 CAUTIN SIGN STICKER <i>?</i>	NEC	\$ 14.00	x
14 AIRCON STICKER <i>new</i>	NEC	\$ 8.00	x
15 LOCK CARRIER BRACKET <i>new</i>		\$ 136.00	x
16 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>new</i>	2	\$ 56.00	x
17 HORN - LH HIGH TONE <i>?</i>		\$ 124.00	x
18 SPRING SHACKLE - LH <i>new</i>		\$ 29.00	x
19 FRONT FENDER - LH <i>Distorted</i>		\$ 758.00	✓
20 FRONT FENDER ATTACHMENT PARTS <i>new</i>		\$ 200.00	x
SUB TOTAL SPARE PARTS		\$ 6,605.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 5881 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER CLOSING ELEMENT - LH ?	\$	49.00 ?	
22 FRONT FENDER BRACKET - LH ?	\$	35.00 ?	
23 DEFORMATION ELEMENT BRACKET - LH ?	\$	49.00 ?	
24 FRONT FENDER BRACKET - LH INNER ?	\$	31.00 ?	
25 FRONT FENDER BRACE - LH FRONT ?	\$	117.00 ?	
26 WHEEL HOUSING LINER - LH <i>new</i>	\$	237.00 <i>x</i>	
27 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	90.00 <i>x</i>	
28 WHEEL SPOILER ?	\$	73.00 ?	
29 WHEEL SPOILER TRIM - LH ?	\$	35.00 ?	
30 STONE CHIP GUARD <i>new</i>	\$	50.00 ✓	
31 FENDER LEDGE TOP COVER - UPPER ?	\$	31.00 ?	
32 FENDER LEDGE TOP COVER - LOWER <i>Repld</i>	\$	23.00 ✓	
33 BONNET IMPACT PROTECTION - CENTRE <i>new</i>	\$	27.00 <i>x</i>	
34 BONNET IMPACT PROTECTION - LH <i>new</i>	\$	28.00 <i>x</i>	
35 BONNET IMPACT PROTECTION - RH <i>new</i>	\$	27.00 <i>x</i>	
36 LED HEADLIGHT - LH <i>cracked</i>	\$	7,693.00 ✓	
37 MAIN LIGHT ELECTRONICS POWER MODULE <i>2</i>	\$	739.00 <i>x</i>	
38 LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$	742.00 <i>x</i>	
39 HEADLIGHT HOSE - LH <i>new</i>	\$	36.00 <i>x</i>	
40 HEADLIGHT COMPENSATING PIECE <i>new</i>	\$	40.00 <i>x</i>	
SUB TOTAL SPARE PARTS	:	\$ 10,152.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 5881 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 HEADLIGHT COMPENSATING PIECE	} new	\$ 40.00	+
42 HEADLIGHT COMPENSATING PIECE		\$ 40.00	+
43 LIFT CYLINDER - LH	?	\$ 208.00	?
44 LIFT CYLINDER CORRUGATED PIPE	new	\$ 92.00	x
45 LOCK CARRIER	new	\$ 1,004.00	+
46 READY MIX COOLANT	new	\$ 91.00	x
47 RADIATOR AIR GUIDE - LH INNER	} new	\$ 28.00	+
48 RADIATOR AIR GUIDE - LH OUTER		\$ 12.00	x
49 TEMPERATURE SENSOR BRACKET		\$ 18.00	x
50 FRONT ALUMINIUM RIM - LH	Not new	\$ 589.00	+
51 FRONT NO PLATE	new	\$ 60.00	+
52 SUNDRIES	?	\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 19,239.00	
TOTAL LABOUR CHARGES	:	\$ 10,452.00	
GRAND TOTAL	:	\$ 29,691.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian L
SURVEYED DATE : 05/11/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : not Authorised , 0\$ Pays

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT