

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

 Model : **Toyota Hiace Commuter 2.8GL AT**

 Registraion No : **PC 7838 Z**

 Chassis No: **GDH2232001106**

 Year of Manufacturing: **2018**

S/No	Qty	Items	Unit Price	Amount
1	1	Tailgate / <i>huc</i>		\$ 2287.30 - 2150.7
2	2	Tailgate Hinge X NN		\$ 88.50 -
3	1	Tailgate Weatherstrip X NN		\$ 474.90 -
4	1	Tailgate Inner Trim Board / CRA		\$ 1280.50 - 425.1
5	1	Tailgate Lock / JM		\$ 376.60 - ✓
6	1	Tailgate Lock Actuator X NN		\$ - -
7	1	Tailgate Logo / NEC		\$ 82.20 - 68
8	1	Tailgate Emblem - Toyota / NEC		\$ 88.90 - 62
9	1	Tailgate Emblem - Hiace / NEC		\$ 88.90 - 62
10	1	Tailgate Emblem - G.L / NEC		\$ 78.90 - 65
11	1	Tailgate Windscreen Moulding / NEC		\$ 96.30 - ✓
12	1	Rear Bumper / DD		\$ 530.90 - ✓
13	2	Rear Bumper Retainer / NEC		\$ 68.60 - ✓
14	4	Rear Bumper Bracket X NN		\$ 19.70 -
15	1	End Panel Inner X <i>repair</i>		\$ 1104.70 -
16	1	End Panel Outer / DD		\$ 559.90 - ✓
17	1	Rear Floor Panel X NN		\$ 2780.50 -

\$ - 4465.1

-25%

\$ -

Total for spare parts \$ - 3348.82

Special Nett

1	1	Rear Bumper Clip set / NN	\$	50.00	\$	50.00	30
2	1	Rear Bumper Reverse Sensor / NW	\$	350.00	\$	350.00	200
3	1	Tailgate Sticker - 70km/h / NEC	\$	35.00	\$	35.00	10
4	1	Tailgate Emblem - JESUS / NEC	\$	65.00	\$	65.00	10

Total for SP \$ 500.00 250

Sub-Total for Parts : \$ 500.00

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	900.00 600
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,200.00 600
3		To check wiring system to facilitate repair and refit the same	\$	60.00 80 X NN
4		Apply rust proofing on the adjacent panels	\$	80.00
5		To supply under coating / putty on parts replaced	\$	50.00 } 60
6		To perform water seepage test after repair	\$	80.00 X NN
7		Remove and refit tailgate mechanism	\$	180.00 } 60
8		Remove and refir rear end panel lining and garnish to facilitate repair	\$	80.00
9		Remove and refit rear reverse sensor	\$	80.00 40
10		Remove and refit rear windscreen	\$	180.00 100
TOTAL AMOUNT :			\$	2,890.00 1460
OVERALL COST:			\$	3,390.00

5 Days.
Lump sum repair
After repair photos.
Gmo Repair.

5058.82

-20%: 4050

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairer
Signature: _____
Date: _____