

CL APPRAISER PTE LTD

24 Penhurst Place, Singapore 556440
 Email: clappraiser@yahoo.com Hp: 9768 8689 Fax: 6452 9783
 Reg No: 201000228E

INVOICE

Muhammad Nasrul Bin Radzuan
 C/o: H I. Cycle Pte Ltd
 No.1 Kaki Bukit Ave 6 #02-58/60
 AutoBay, Singapore 417883

Invoice No: CL/200512

Ref No: HLC/10/2001/TP

Date: 19 October 2020

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES: - SURVEY INSPECTION FOR VEHICLE NO. <u>FBP 9089 J</u> - RESURVEY INSPECTION - DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS) - TRANSPORTATION	
GRAND TOTAL	S\$ 579.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Pensihurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Muhaarunad Nasrul Bin Radzuan
C/o: H I. Cycle Pte Ltd
No 1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Date : 19 October 2020
Our ref: HLC/10/2001/TP

Accident Date : 29 September 2020
Inspection Date : 07 October 2020
Repairer Name : H I. Cycle Pte Ltd
No.1 Kaki Bukit Ave 6 #02-58/60
AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBP 8089 J
Make / Model : Yamaha Aerox
Chassis No : MH3SG4640KJ055898
Engine No : G318E0104791

Year / Capacity : 2019 / 155 cc
Colour : Black
Mileage : 19976

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	Mittas	120/90-14	5 mm	Sport
Rear	Mittas	150/70 -14	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s and n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 99 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,500.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: FBP 8089 J

Our Ref No: HLC/10/2001/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front fork assy X SVC	Damage	\$ 980.00	\$ 980.00	
1	Fork under bracket X SVC	Damage	\$ 255.00	\$ 255.00	
1	Headlamp ✓	Damage	\$ 550.00	\$ 550.00	485
1	N/s side mirror ✓	Damage	\$ 120.00	\$ 120.00	✓
1	Handle-bar ✓	Damage	\$ 185.00	\$ 185.00	135
1	Handle-bar balancer (1 set) ✓	Damage	\$ 80.00	\$ 80.00	✓
1	N/s brake lever ✓	Damage	\$ 52.00	\$ 52.00	✓
1	Front n/s signal ✓	Damage	\$ 95.00	\$ 95.00	✓
1	Radiator SVC	Intact	\$ 525.00		
1	Radiator grille X SVC	Damage	\$ 155.00	\$ 155.00	
1	N/s footstep panel ✓	Damage	\$ 120.00	\$ 120.00	✓
1	Exhaust assy X Repair	Damage	\$ 880.00	\$ 880.00	
1	Exhaust protector ✓	Damage	\$ 78.00	\$ 78.00	✓
1	Rear signal X SVC	Damage	\$ 80.00	\$ 80.00	
1	Rear n/s footrest X SVC	Damage	\$ 65.00	\$ 65.00	
1	Drove belt cover ✓	Damage	\$ 340.00	\$ 340.00	✓
1	Main stand ✓	Damage	\$ 145.00	\$ 145.00	✓
1	Side stand ✓	Damage	\$ 95.00	\$ 95.00	40
1	Pairing cover (1 set) ✓	Damage	\$ 1,250.00	\$ 1,250.00	1050
			\$ 6,050.00	\$ 5,525.00	2740
		Less 10%	\$ 605.00	\$ 552.50	
	Total Cost - List Items		\$ 5,445.00	\$ 4,972.50	2466

SPECIAL NETT ITEMS

1	Number plate (1 set) X SVC	Damage	\$ 28.00	\$ 28.00	
1	Rear box ✓	Damage	\$ 350.00	\$ 350.00	280
1	Rear box bracket X SVC	Damage	\$ 150.00	\$ 150.00	
1	Delivery bag X SVC	Damage	\$ 550.00	\$ 550.00	
	Total Cost - Special Nett Items		\$ 1,078.00	\$ 1,078.00	

Total cost of parts

\$ 6,523.00 \$ 6,050.50

Vehicle Registration No: FBP 8089 J

Our Ref No: HLC/10/2001/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,523.00	\$ 6,050.50

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00	35
2	To check electrical system, wire harness and focus headlamp	\$ 80.00	\$ 50.00	×
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00	200
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00	×

235

GRAND TOTAL

\$ 7,483.00	\$ 6,900.50
--------------------	--------------------

2981

-20%: 2400

3 days

Vehicle Registration No: FBP 8089 J

Our Ref No: HLC/10/2001/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,500.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048530
Phone: +65 8224 0010 Fax: +65 8224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M40017735

SEARCH RESULTS

Our Ref No: GR-20-119863

Date of Request: 05/10/2020

Your Ref No:

HQ - FBP8089J

JusEquity Law Corporation
133 New Bridge Road
#10-03, Chinatown Point
Singapore 059413

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 29/09/2020
Place of Accident: TAMPINES AVE 7
Client Vehicle No: FBP8089J

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SLV5682J	JUNCTION OF TAMPINES AVE 7 & TAMPINES CENTRAL 7	29/09/2020 18:50

Thank You,

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-03, Singapore 048089
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-20-119863

Date of Request: 05/10/2020

Your Ref No.

HC - FBF8089J

JusEquity Law Corporation
 133 New Bridge Road
 #10-03, Chinatown Point
 Singapore 059413

Dear Sir/Madam,

Your Search Criteria

Date of Accident: 29/09/2020
 Place of Accident: TAMPINES AVE 7
 Client Vehicle No: FBF8089J

DESCRIPTION	AMOUNT (\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No. M400017735

TAX INVOICE

Our Ref No. GR-20-119864

Date of Request: 05/10/2020

Your Ref No.

HC - FBP6088J

JusEquity Law Corporation
133 New Bridge Road
#10-03, Chinatown Point
Singapore 059413

Dear Sir/Madam,

Date of Accident: 29/09/2020

File No: FBP6088J

Place of Accident: TAMPINES AVE 7 JUNCTION

Involving Vehicle No: SLV6682J

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLV6682J	TAMPINES AVE 7 JUNCTION	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy of contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature

For GIARMC Official use

File.

☒ GIRO ☐ Cash ☐ Cheque















































