

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 09 Nov 2020

Preliminary Advice

Vehicle No	: GBG6355B	Accident Date	: 01/11/2020
Make	: MERCEDES-BENZ VITO 114	Policy No.	: 0999993880
Assignment Date	: 06/11/2020	Excess	: S\$0.00
Date of Inspection	: 06/11/2020	Est. Duration of Repair	: 4
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,073.10
Revised Amount	:S\$	4,570.55
Check Items (Estimated)	:S\$	1,355.75
Total	:S\$	5,926.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	25,282.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,718.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :