




Registration No. 192600045M GST, Registration No. M2-0000551-1
 Singapore
 6272 8828
 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : B9 4833
 Date Estimated : 02/11/2020
 Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Sime Darby Services Private Limited
 305 Alexandra Road
 #02-01 Vantage Automotive Centre
 Singapore 159942

- ACCOUNT - 35
 India Int'l Insurance Pte Ltd
 64 Cecil Street #04/05
 IOB Building
 Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4852D	WBA2D920605E91546	01/12/2017		0

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST INDIA INS-SLC2159E DOA. 30.10.20	0.00
TO REMOVE AND REPLACE REAR BUMPER, TAILGATE PANEL, REAR END PANEL AND ALL AFFECTED AREAS. @350 X 3	1050 1,800.00
TO RESPRAY AND PUTTY TAILGATE PANEL, REAR BUMPER, REAR END PANEL AND ALL AFFECTED AREAS. @350 X 3	1050 1,500.00
TO CARRY OUT BODY CAVITY PRESERVATION.	90 180.00
TO CONDUCT ECU PROGRAMMING CHECK AND TO CLEAR FAULT CODES (NETT)	300 380.00
TO TRANSFER AND REFIX REAR TAILGATE FITTINGS, TRIM AND MECHANICAL COMPONENTS (NETT)	150 300.00
TO REMOVE AND REAR WINDSCREEN GLASS, CONDUCT WATER TEST LEAKS (NETT)	300 380.00
TO REMOVE AND REINSTALL REAR SENSORS AND CONDUCT DISTANCE SETTINGS.	80 150.00
TO SUPPLY AND INSTALL REAR WINDSCREEN GLASS SOLAR FILM (NETT)	Xm ? 350.00

Total Labour 1: 5,040.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
	TAILGATE PANEL <i>bt</i>	1	1,355.59	5.00	1,287.81
	TAILGATE RUBBER BEADING <i>xscr</i>	1	171.18	5.00	162.62
	REAR WINDSCREEN GLASS <i>? photo ? xm</i>	1	644.45	5.00	612.23
	REAR WINDSCREEN GLASS SEALANT <i>ru</i>	2	147.34	5.00	279.95
	REAR BUMPER <i>ca</i>	1	1,170.90	5.00	1,112.35
	REAR BUMPER INNER GUIDE LH <i>? xscr</i>	1	73.01	5.00	69.36
	REAR BUMPER INNER GUIDE RH <i>? xscr</i>	1	73.01	5.00	69.36
	REAR BUMPER SIDE GUIDE LH <i>? xscr</i>	1	73.01	5.00	69.36
	REAR BUMPER SIDE GUIDE RH <i>? xscr</i>	1	73.01	5.00	69.36
	REAR BUMPER REINFORCEMENT <i>? xscr</i>	1	515.65	5.00	489.87
	SET MOUNTS PDC SENSOR REAR <i>? xscr</i>	1	72.23	5.00	68.62
	TAILGATE LOGO EMBLEM <i>ru</i>	1	85.20	5.00	80.94

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : B9 4833
 Date Estimated : 02/11/2020
 Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU4852D	WBA2D920605E91546	01/12/2017		0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
	SUPPORT ? <i>xsu</i>	1	54.20	5.00	51.49
	REAR BUMPER TOWING COVER <i>xsuc</i>	1	51.23	5.00	48.67
	REAR END PANEL <i>repair</i>	1	399.84	5.00	379.85
	INTERIOR TAIL TRIM ? <i>xsu</i>	1	314.16	5.00	298.45
	REAR BUMPER REVERSE SENSOR ? <i>xsuc</i>	2	440.30	5.00	836.57

Total Parts : 5,986.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resu
Hy 90010068
6 days
18/11/2020 @ 1400
Resu before paint

Customer Name & Signature / Company Stamp

Date

Labour 1	:	5,040.00
Parts	:	5,986.86
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	771.88
Grand Total	:	11,798.74

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLU4852D

RO Number: B9 55122

24-11-20

NO.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1					10%	\$0.00
2					10%	\$0.00
					10%	\$0.00
					10%	\$0.00
					10%	\$0.00
					10%	\$0.00
					10%	\$0.00
Parts Total:						\$0.00

NO.	Supplementary Labour Charges	Price
1	TO SUPPLY REAR NUMBER PLATE bt /	\$70.00
2		
3		
4		
5		
Total Labour:		\$70.00
Total Parts & Labour:		\$70.00
GST @ 7%:		\$4.90
Grand Total:		\$74.90

Raised By Technician	Approved By CSA <i>Vion Lim</i>	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	---------------------------------------	-----------------------------------	--------------------------------------