

SIN HO AUTO

Blk 3020A #01-33 Ubi Road 1 Singapore 408714

INVOICE

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #04/#05/#06-02
IOB BUILDING
Singapore 049711

Date: 19-Dec-20

Accident date: 05th NOV 2020
Final Bill For Vehicle No: GBE8677U NISSAN CAB STAR 3.0

Descriptions	AMOUNT
Lump Sum repair cost as recommended by LKK AUTO CONSULTANTS PTE LTD	\$2,500.00
Total	\$2,500.00

S/DLR S: TWO THOUSAND FIVE HUNDRED ONLY

