



13th Nov 2020

EQ Insurance Company Ltd.
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Attention: Motor Claims Department

Dear Sir/ Madam,

Quotation for supply parts, necessary equipment and tools for the repair of PC3460E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Description	Qty	U/Price	Total Price	Remark
Front bumper <i>Dep</i>	1 pc	\$657.60	\$657.60	<i>550</i>
Front bumper retainer <i>BR</i>	2 pcs	\$335.35	\$670.70	<i>200</i>
Front fog lamp RH <i>X SVC</i>	1 pc	\$121.10	\$121.10	<i>X</i>
Front head lamp RH <i>SCR</i>	1 pc	\$1060.60	\$1060.60	<i>790</i>
		Total Parts :	\$2'510.00	<i>1,540</i>
				<i>2</i>
To remove & replace damage parts, apply putty & spray painting	1 job	\$920.00	\$920.00	(3 working days)
			<i>600</i>	<i>600</i>
		Total Labour:	\$920.00	
		Sub-Total:	\$3'430.00	
		7% GST	\$240.10	
		Grand Total	\$3'670.10	

Repair day - 2 days

Thanks,

Wong Kok Fu
Asst. Workshop Manager

LIS

After paint photo

Sun Pin (46)

17/11/2020

TP art the progre

Sunpin@lkkauto.com

1,540
- 25%
1,155
600
1,755
- 20%
1,404

LIS
\$1,400
2 days