



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2103902

INV Date 02/06/2021

Reference CS/EQI20012187/Dtd3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 7047D
Insured Veh. SMU 4783H
Claim No. DM20HO01647/JT
Policy No.
Accident Date 04/11/2020
Inspection Date 09/11/2020

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI20012187/Dtd3e2 Date: 02/06/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMU 4783H	Veh. Inspected	SHD 7047D
Policy No.		Coverage (\$)	0.00
Claim No.	DM20HO01647/JT	Excess (\$)	0.00
Assign From	JAIME TAY	Assign Date	06/11/2020
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU078585	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/11/2020	Inspection Date	09/11/2020
Survey held at	BLK 9 SIN MING SECTOR C #01-42		
Repairer	BIFROST AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7047D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	2,265.90	2,265.90
1	BONNET RUBBER (LH)	SERVICEABLE	35.70	-
1	BONNET RUBBER (RH)	SERVICEABLE	35.70	-
2	BONNET HINGE (LH/RH) @\$126.70	BENT	253.40	253.40
1	BONNET LOCK	BENT	142.40	142.40
1	BONNET ABSORBER (LH ONLY)	NOT NECESSARY	61.60	-
1	BONNET INSULATOR	BENT	202.50	202.50
10	BONNET INSULATOR CLIP	NECESSARY	36.80	36.80
1	BONNET SEAL	SERVICEABLE	31.90	-
1	BONNET INSULATOR CLIPS	REPEATED	15.00	-
1	BONNET CABLE	NOT NECESSARY	69.60	-
1	RADIATOR GRILLE H EMBLEM	BROKEN	129.50	129.50
1	RADIATOR GRILLE	BROKEN	1,480.00	1,110.10
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	379.20	379.20
1	FRONT BUMPER REINFORCEMENT	BUCKLED	588.40	588.40
2	FRONT BUMPER GRILLE (LH/RH) @\$149.20	DISLODGE / CUT	298.40	298.40
1	FRONT BUMPER LIP	TORN	152.00	152.00
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$44.80	NOT NECESSARY	89.60	-
2	FRONT BUMPER BRACKET (LH/RH) @\$49.20	O/S BENT / N/S NOT NECESSARY	98.40	49.20
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	76.20	-
2	FRONT BUMPER GRILLE AIR DUCT (LH/RH) @\$126.20	DISLODGE / BROKEN	252.40	252.40
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
2	HEADLAMP (LH/RH) @\$2776.00	BROKEN / DISLODGE	5,552.00	2,776.00
1	HEADLAMP SUPPORT TOP COVER	BROKEN	222.60	222.60
1	THROTTLE BODY ASSY	NOT NECESSARY	936.90	-
1	RADIATOR	BENT / PUNCTURE	1,637.20	708.50
2	RADIATOR GUARD (LH/RH) @\$76.50	O/S BROKEN / N/S NOT NECESSARY	153.00	76.50

Report Ref No. CS/EQI20012187/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	BROKEN	1,194.20	792.95
1	RADIATOR EXPANSION TANK	NOT NECESSARY	163.80	-
2	HORN UNIT (LH/RH) @\$72.30	BROKEN	144.60	144.60
1	HORN WIRE	TORN / SOCKET BROKEN	156.60	156.60
2	FRONT FENDER (LH/RH) @\$566.30	DENTED	1,132.60	1,132.60
1	FRONT FENDER APRON PANEL (LH)	TO REPAIR SEE LABOUR	637.00	-
2	FRONT FENDER SHIELD (LH/RH) @\$174.90	SERVICEABLE	349.80	-
1	AIRCON CONDENSER	BENT / PUNCTURE	947.80	947.80
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	133.70	-
1	FRONT WINDSCREEN PILLAR OUTER (LH)	TO REPAIR SEE LABOUR	1,535.90	-
1	ENGINE UNDER COVER	DISLodge / BROKEN	334.60	334.60
1	INTER COOLER	BENT / PUNCTURE	1,032.50	1,032.50
1	ENGINE TOP COVER	NOT NECESSARY	321.70	-
1	AIR BAG COMPLETE	NOT NECESSARY	2,348.50	-
1	AIR BAG CONTROL MODULE	ACTIVATED	1,894.00	1,894.00
1	STEERING AIR BAG	ACTIVATED	1,150.60	1,150.60
1	SENSOR ASSY IMPACT - FRONT IMPACT	NOT NECESSARY	1,180.50	-
2	AIR BAG SENSOR	ACTIVATED	1,160.00	1,160.00
1	DEVICE ASSY - SWIRL (ADDITIONAL)	BROKEN	1,367.20	835.10
1	RADIATOR HOSE UPPER (ADDITIONAL)	DEFORMED	229.50	229.50
1	RADIATOR HOSE LOWER (ADDITIONAL)	NOT NECESSARY	135.60	-
1	AIR CLEANER ASSY (ADDITIONAL)	BROKEN	325.00	325.00
1	AIR DUCT (ADDITIONAL)	BROKEN	171.70	171.70
1	AIRCON SUCTION & LIQUID HOSE (ADDITIONAL)	BENT	549.10	549.10
1	AIRCON DISCHARGE HOSE (ADDITIONAL)	SERVICEABLE	194.40	-
2	FRONT SAFETY BELT ASSY (LH/RH) @\$477.20 (ADDITIONAL)	ACTIVATED	954.40	954.40
1	WIPER GARNISH (ADDITIONAL)	BROKEN	476.60	222.60
1	WIPER SPARE TANK ASSY (ADDITIONAL)	CRACKED / DEFORMED	486.70	61.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT CHASSIS MEMBER (LH/RH) @\$1060.70 (ADDITIONAL)	N/S BENT / O/S TO REPAIR SEE LABOUR	2,121.40	1,060.70
1	EGR VALVE & PIPE ASSY (ADDITIONAL)	NOT NECESSARY	2,685.50	-
1	STARTER MOTOR ASSY (ADDITIONAL)	SOCKET BROKEN	950.00	950.00
	LESS 20% DISCOUNT		-8,724.28	-5,141.93
			34,897.12	20,567.72
	<u>SPECIAL NETT ITEMS</u>			
1	COOLANT (SN)	NECESSARY	45.00	45.00
1	FRONT NUMBER PLATE (SN) }	DISLODGE / BROKEN	25.00	45.00
1	FRONT NO. PLATE TRIM COVER (SN) }	DISLODGE / BROKEN	30.00	-
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NECESSARY	200.00	200.00
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	45.00	-
1	GEARBOX (SN) (ADDITIONAL)	MTG BROKEN	4,000.00	4,000.00
			4,345.00	4,290.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER APRON PANEL (LH), FRONT WINDSCREEN PILLAR OUTER (LH) AND FRONT CHASSIS MEMBER RH.		1,600.00	1,200.00
	SPRAY PAINTING CHARGE.		1,400.00	800.00
	WIRING CHARGE.		180.00	30.00
	TUFF KOTE.		160.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX RADIATOR.		90.00	50.00
	REMOVE / REFIX AIRCON & REFILL GAS.		130.00	80.00
	REMOVE / REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	REMOVE / REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX ENGINE.		600.00	250.00
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	350.00	-
	REMOVE / REFIX AIR BAG / STEERING WHEEL / DASHBOARD / SEAT.		550.00	180.00

Report Ref No. CS/EQI20012187/Dtd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	180.00
			5,930.00	2,810.00
	GRAND TOTAL		45,172.12	27,667.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				18,000.00

Report Ref No. CS/EQI20012187/Dtd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 9-Nov-20


INSURANCE: EQ

MODEL: HYUNDAI I40

VEHICLE NO.: SHD 7047 D (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
DEVICE ASSY - SWIRL <i>broken</i> 835.10	1	\$1,367.20	\$1,367.20
RADIATOR HOSE UPPER <i>deflower</i>	1	\$229.50	\$229.50
RADIATOR HOSE LOWER <i>H</i>	1	\$135.60	\$135.60
AIR CLEANER BOTTOM ASSY <i>broken</i>	1	\$325.00	\$325.00
AIR DUCT <i>broken</i>	1	\$171.70	\$171.70
AIRCON SUCTION & LIQUID HOSE <i>H</i>	1	\$549.10	\$549.10
AIRCON DISCHARGE HOSE <i>SN</i>	1	\$194.40	\$194.40
FRONT SAFETY BELT ASSY (LH/RH) <i>actinder</i>	2	\$477.20	\$954.40
WIPER GARNISH <i>broken</i> 222.60	1	\$476.60	\$476.60
WIPER SPARE TANK ASSY <i>crack/deflower</i> 61.90	1	\$486.70	\$486.70
FRONT CHASSIS MEMBER (LH/RH) <i>H/S bt o/s rep</i>	2	\$1,060.70	\$2,121.40
STARTER MOTOR ASSY <i>Socket broken</i>	1	\$950.00	\$950.00
EGR VALVE & PIPE ASSY <i>H</i>	1	\$2,685.50	\$2,685.50
GEARBOX <i>momentary broken</i>	1	\$15,800.00	\$15,800.00
	SN	4000.00	4000.00
SUB TOTAL			\$26,447.10
LESS 20%			\$5,289.42
DISCOUNTED TOTAL			\$21,157.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

you
2kk Auto


5360.00
200, 4288.00
SN 4000.00

8288.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2020 14:44
Date Of Accident	04/11/2020 23:30
Exact Location Of Accident	ANG MO KIO AVE 8 X BISHAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD7047D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	JUMALI BIN KASSIM
NRIC No	SXXXX314G
Date Of Birth	14/05/1953
Occupation	OUTDOOR
Date Of Driving Pass	15/10/1981
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97707610
Fax Number	
Contact Number	
EMail Address	JUMALI_K@HOTMAIL.COM

Address BLK 778 YISHUN AVENUE 2
#03-1567

Postcode 760778

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions DRIZZLING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1
NAME: : -
GENDER: : MALE

Passenger 2
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20201105/2052 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: -

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMU4783H

Vehicle Make/Model/Colour MAZDA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver	LOW JIA YI
NRIC/Passport Number	
Contact Number	94528761
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LH
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	JUMALI BIN KASSIM
Approximate Age	
Injuries Sustain	NECK, LOWER BACK SPRAIN
Injured person in which vehicle?	SHD7047D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/11/2020 12:52		Vide Report No.:		Station Diary No.: 87	
Informant's Particulars					
Name of Informant: JUMALI BIN KASSIM			Address: APT BLK 778 YISHUN AVENUE 2 #03-1567 SINGAPORE 760778		
ID Type / ID No.: NRIC NO / S0163314G			Contact No.: Home/Office: Mobile: 97707610		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 67	Date of Birth: 14/05/1953	Type of Informant: Driver		
Race: Javanese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/11/2020 23:30	Type of Location: X-Junction
Location: ANG MO KIO AVENUE 8				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD7047D	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Seriously Damaged	2
SMU4783H	Car	MAZDA	MAZDA3 4DR 1.5 AT M-HYBRID ELEGANCE	Grey	Seriously Damaged	1



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20201105/2052

CONTINUATION OF REPORT

Brief Details.

1) On 04 November 2020 at about 2330hrs, I was driving a vehicle with the registration number (SHD7047D) with two passenger. I am travelling at the third lane on a five lane road from Ang Mo Kio Avenue 8 towards Bishan. As I was approaching the cross junction between Ang Mo Kio Avenue 8 and Ang Mo Kio Avenue 1. I observed that the traffic light was green as such I proceed to cross the junction towards Bishan. However, there was a vehicle with the registration number (SMU4783H) travelling on the opposite side of the road from Bishan. The vehicle (SMU4783H) make a right turn towards Ang Mo Kio Avenue 1 when the arrow signal light was red.

2) The vehicle came in-front of me while I was moving straight and the vehicle was turning right. I am unable to stop my vehicle in time and we collided with one another. The traffic police was at the location and both of the vehicle was towed away. I checked with everyone at the location and was informed that there are no injuries.

3) On 05 November 2020, I felt some discomfort on my body and went to the Hospital. The diagnosis was neck and lower back strain and I was given 5 days of medical certificate. I wish to add on that I received a call from the employer of the passenger and asked for my personal particular because the passengers forget to ask during the traffic accident as the female passenger believed to had injured during the accident.

Passengers

- * Kenny Ching Yang Fau / G8371677R / Male / 8307 5713
- * May Sabai Pwint / G5102954R / Female / 9795 4030



**SINGAPORE
POLICE FORCE**



T/20201105/2052

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20201105/2052

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 1 GAN WEI LEONG, ALASTAIR	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/11/2020 12:52
Officer In Charge Of Case: TP / GIT / Contact No.:	Classification Of Case:

Authentication Stamp
NP168


 Signature: 
 Singapore Police Force

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE. LTD.
CO. REG. NO. 19930382112

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 05.11.2020
@14:00 hrs


Reporting Centre Personnel's Signature
Name: Regina
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20201105/2052
--

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 05.11.2020 @14:00 hrs


Reporting Centre Personnel's Signature
Name: Regina
NRIC/FIN No.:



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7047D

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7047D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 7047D

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

