

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5862K**AAD2011-008***Not Ashanti
L/Sy \$1500h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 NOV 2020**SHC5862K**

VF1ABL15AUC281456

RENAULT

LATITUDE

31/10/2020

AIG

6/3/2015

PART

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER BRACKET FRT LH (~~Headlamp Lower~~)
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE FRAME
- 1 RADIATOR GRILLE BADGE "RENAULT"
- 1 FRAME FULL SUPPORT PANEL
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT LH
- 1 HEADLAMP LH
- 1 FENDER PANEL FRT LH
- 1 FENDER BRACKET LOWER LH
- 1 FENDER BRACKET FRT LH
- 1 WHEELARCH FRT LH
- 1 AIR CLEANER BOX
- 1 AIR CLEANER HOSE
- 1 AIR CLEANER LOWER

LIST		
<i>Bur / Cat</i>		
\$		747.20 ✓
\$	<i>Sh</i>	344.70
\$	<i>Sh</i>	101.40
\$	<i>Sh</i>	116.47
\$	<i>Sh</i>	969.90
\$	<i>Sh</i>	686.00
\$	<i>Sh</i>	225.36
\$	<i>R</i>	592.70
\$	<i>Sh</i>	207.21
\$	<i>R</i>	663.70
\$	<i>Sh</i>	101.40
\$	<i>mgmt</i>	743.60
\$	<i>R</i>	437.10
\$	<i>Sh</i>	11.80
\$	<i>Sh</i>	106.40
\$	<i>Sh</i>	191.40
\$	<i>Sh</i>	464.20
\$	<i>Sh</i>	175.85
\$	<i>Sh</i>	271.26

TOTAL	\$	7,157.65
10%	\$	715.77
	\$	6,441.89

Special Nett

- 1 BUMPER CLIP FRT \$ *R 90.00*
- 1 BUMPER RETAINER CLIP FRT \$ *W 75.00 X*

Trans-cab Auto Services Pte Ltd

AAD2011-008

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5862K

1 WHEELARCH CLIP FRT	\$	<i>na</i>	75.00	X
1 FENDER SCREW	\$	<i>na</i>	60.00	X
1 FRT NUMBER PLATE WITH HOLDER	\$	<i>na</i>	120.00	<i>45.00</i>
TOTAL	\$		240.00	

TOTAL PARTS	\$	6,681.89
--------------------	-----------	-----------------

LABOUR

To rust-proofing and apply undercoat of the affected areas.	\$	<i>na</i>	230.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
Putty and spray painting of the affected portion.	\$		1,400.00	<i>2200</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	<i>2000</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>200</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
TOTAL	\$		4,360.00	

Over All Total	\$	11,041.89
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days*20 Days**1 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: