



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM20012197/Bba3q2 Date: 17/05/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMM 7427J	Veh. Inspected	SMF 7088R	
Policy No.	P2341060	Coverage (\$)	0.00	
Claim No.	S0M02VXU	Excess (\$)	0.00	
Assign From		Assign Date	06/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTNGF3DH108018910	Colour	BLACK	
Odometer	191005 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	WEST LAKE	7 mm	
L/H Front Tyre	235/50 R18	WEST LAKE	7 mm	
R/H Rear Tyre	235/50 R18	WEST LAKE	7 mm	
L/H Rear Tyre	235/50 R18	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2020	Inspection Date	09/11/2020	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	