

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LEY CHOON CONSTRUCTIONS AND
ENGINEERING PTE LTD
3 SUNGEI KADUT DRIVE KANJI
INDUSTRIAL ESTATE
SINGAPORE 729556

Contact : 93816785

ESTIMATE

Repair Code : CLM15083

Date in : 05/11/2020

Vehicle Num. : GBB2451J

Model : TOYOTA DYNA 150 MANUAL 3SEATER

Chassis/Eng# : JTFAT35Y40K200144/1KD1875499

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR NUMBER PLATE LAMP L/R ✓ <i>CR</i>	2	60.70	97 121.40
REAR NUMBER PLATE PANEL ✓ <i>BT</i>	1	228.60	119.5 228.60
REAR NUMBER PLATE PANEL BRACKET ✓ <i>BT</i>	1	57.10	57.10
REAR RUBBER STOPPER BRACKET R/L <i>LH - BT, RH X NN</i>	2	98.60	98.6 197.20
REAR RUBBER STOPPER R/L <i>LH - cut, RH X NN</i>	2	43.10	43.1 86.20
REAR TAILGATE ✓ <i>Buc</i>	1	1116.70	✓ 1,116.70
REAR TAILGATE FLIP LOCK HANDLE L/R <i>LH - BT, RH X NN</i>	2	115.90	115.9 231.80
REAR TAILGATE HINGES X <i>Repair</i>	4	104.00	X 416.00
REAR TAILGATE LOWER PANEL ✓ <i>Buc</i>	1	585.50	✓ 585.50
REAR TAILLAMP BRACKET R/L ✓ <i>BT</i>	2	61.80	✓ 123.60
REAR TAILLAMP R/L ✓ <i>CR</i>	2	251.30	✓ 502.60
Subtotal before discount		2802.5	3,666.70
Percentage discount 25%		2101.88	916.68
Sub-total 1			2,750.03
REAR FLOOR ALUMINIUM CHECKER BOARD <i>BT - photo</i>	1	1000.00	550 1,000.00
REAR FLOOR ALUMINIUM CHECKER BOARD REPAIR KIT X <i>NN</i>	1	100.00	X 100.00
REAR HOLDER BRACKET ✓ <i>505</i>	1	500.00	150 500.00
REAR NUMBER PLATE ✓ <i>505</i>	1	25.00	15 25.00

*** This is a computer-generated document which requires no signature.***

LEI MOTIVE PTE LTD

16 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Phone 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

LEY CHOON CONSTRUCTIONS AND
 ENGINEERING PTE LTD
 3 SUNGEI KADUT DRIVE KANJI
 INDUSTRIAL ESTATE
 SINGAPORE 729556

Contact : 93816785

ESTIMATE

Repair Code : CLM15083

Date in : 05/11/2020

Vehicle Num. : GBB2451J

Model : TOYOTA DYNA 150 MANUAL 3SEATER

Chassis/Eng# : JTFAT35Y40K200144/1KD1875499

REAR REVERSE SENSOR / DM	1	250.00	200	250.00
REAR STEP BRACKET / BT	1	450.00	250	450.00
REAR TAILGATE '6PAX' STICKER	1	25.00	10	25.00
REAR TAILGATE '70KM/H' STICKER	1	25.00	10	25.00
REAR TAILGATE ART WORK STICKER	1	280.00	50	280.00

Subtotal before discount 2,655.00

Percentage discount 0% 0.00

Sub-total 2 2,655.00

Parts-total 1235 5,405.03

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 1280 2,440.00

Parts & Labour Total 7,845.03

4616.88

-20%: 3700

*** This is a computer-generated document which requires no signature.***

page 2

5 Days.
 1up sm repair.
 After repair photos.
 Gmc Repair.
 09/11/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____