



## ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: FAX:		NAME: Mr A Suppiah Rajah ADDRESS: Blk 406 #04-303 FAJAR ROAD Singapore 670406 TEL: 98585801		WIP: 22080 EXCESS: DATE: 5-Nov-20	
VEH NO:	SMQ4938A	DATE IN:		CONTACT PERSON:	Jobi 63310682
CHASSIS NO:	JM6KE1072G0319831	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	CX-5	DATE REG.:	19-Jun-15	POLICY NO.:	

## NATURE OF WORKS

## Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	FRONT FENDER RHS <i>buc</i>	MKD53-52-111A	1				\$ 512.30
2	STAY RHS, FRONT FENDER <i>neu</i>	MKDY3-52-10Y	1				\$ 60.00
3	MUDGUARD RHS <i>? x3</i>	MKD53-56-130H	1				\$ 128.40
4	FASTENER, MUDGUARD <i>neu</i>	MB45A-56-146A	20				\$ 60.00
5	GARNISH RHS, FRONT FENDER <i>de</i>	MKD53-51-W20C	1				\$ 186.70
TOTAL PARTS							\$ 947.40
TOTAL PARTS COST							\$ 947.40

## SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	0	0	0				\$ -
2	0	0	0				\$ -
3	0	0	0				\$ -
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

## Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT FENDER RH.REPAIR FRONT DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	630	\$ 1,650.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT FENDER RH AND FRONT DOOR RH.	1320	\$ 1,575.00
3	MZ-BR-WHEAL1	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. <i>(report copy)</i>	NETT	\$ 560.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150/	\$ 250.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUIC)	150/	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250/	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 30/100.00
			TOTAL LABOUR	\$ - \$ 4,735.00
			TOTAL PARTS	\$ - \$ 947.40
			TOTAL	\$ - \$ 5,682.40
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

### SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A			
2	#N/A			
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

#### REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LT

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rasul*  
Hp 90010068

5 days

09/11/2020 @ 1320

Resy before print