

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

keep reference



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0842/2020/NS

6-Jan-21

CHANG


1 of 1

SMG 8340 A

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISMANTLE AND RENEW BONNET.	\$ 800.00 500	
2	TO RESPRAY BONNET.	\$ 900.00 550	
Parts			
1	BONNET	\$ 3,312.00 <i>h-</i>	
2	BONNET IMPACT PROTECTION - CENTER	\$ 28.00 <i>rec-</i>	
3	BONNET IMPACT PROTECTION - LH/RH	\$ 56.00 <i>rec-</i>	
4	OUTER TEMPERATURE SENSOR BRACKET	\$ 19.00 <i>cu-</i>	
GRAND TOTAL		\$ 5,115.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Rame
06/01/2021

@1620

Car-in 5/1/21 mp=56410

Kiam/Keng


 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER Deformed	\$	2,251.00	✓
2 FRONT BUMPER FIXING PARTS Ne u	\$	402.00	+
3 FRONT BUMPER SECURING STRIP Ne u 2	\$	70.00	+
4 FRONT BUMPER GRILLE - CENTRE Ne u	\$	194.00	+
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE Ne u	\$	225.00	+
6 FRONT BUMPER SPOILER ? Ne u	\$	529.00	+
7 FRONT BUMPER AIR GUIDE - LH	\$	62.00	+
8 RADIATOR GRILLE One bad	\$	2,300.00	✓
9 ULTRASOUND SENSOR SUPPORT - LH/RH Ne u 2	\$	102.00	✓ photo *
10 RADIATOR GRILLE COVER - UPPER Ne u	\$	187.00	+
11 FRONT BUMPER AIR GUIDE GRILLE - LH Ne u	\$	468.00	+
12 FRONT BUMPER CARRIER ?	\$	795.00	?
13 FRONT BUMPER FOAM FILLER PIECE ? can	\$	123.00	?
14 FRONT BUMPER TOP COVER Ne u	\$	126.00	+
15 CAUTION SIGN STICKER ? Ne u	NEC \$	14.00	+
16 AIRCON STICKER	NEC \$	8.00	+
17 LOCK CARRIER BRACKET Ne u	\$	136.00	+
18 LOCK CARRIER BRACKET SUPPORT - LH/RH Ne u 2	\$	56.00	+
19 FRONT PARKING AID SENSOR - INNER Ne u	\$	242.00	+
20 FRONT PARKING AID SEAL RING Ne u 4	\$	14.00	+
SUB TOTAL SPARE PARTS	:	\$	8,304.00



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 HORN - LH HIGH TONE		\$ 124.00	X
22 SPRING SHACKLE - LH		\$ 29.00	X
23 LED HEADLIGHT - LH		\$ 7,812.00	X
24 LIFT CYLINDER - LH		\$ 196.00	X
25 RADIATOR AIR GUIDE - INNER		\$ 31.00	X
26 RADIATOR AIR GUIDE - OUTER		\$ 16.00	X
27 FRONT NO PLATE	S/N	\$ 60.00	✓
28 SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 16,872.00	
TOTAL LABOUR CHARGES	:	\$ 3,272.00	
GRAND TOTAL	:	\$ 20,144.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.