

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0842/2020/NS
DATE	:	4-Nov-20
WIP	:	56410

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR DEBETS FRANK JOZEF CHRISTIAAN
ADDRESS	:	1D SHELFORD ROAD
	:	#02-23
	:	SINGAPORE 286889
TELEPHONE	:	HP +65 97438778
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800152156
VEHICLE NO	:	SMG 8340 A
MODEL CODE	:	AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR	:	31/12/2018
ENGINE NO	:	CVK 073246
CHASSIS NO	:	WAUZZZF58KA010127
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	6-Oct-20
PLACE OF ACCIDENT	:	CORNER OF SHELFORD RD & DUNEARN RD



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 8340 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,200.00	500 ✓
4	TO RESPRAY FRONT BUMPER.		\$ 1,000.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,272.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS

1 FRONT BUMPER		\$	2,251.00 ✓	1800.80
2 FRONT BUMPER FIXING PARTS		\$	402.00 +	
3 FRONT BUMPER SECURING STRIP	2	\$	70.00 +	
4 FRONT BUMPER GRILLE - CENTRE		\$	194.00 +	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$	225.00 +	
6 FRONT BUMPER SPOILER		\$	529.00 +	
7 FRONT BUMPER AIR GUIDE - LH		\$	62.00 +	
8 RADIATOR GRILLE		\$	2,300.00 ✓	1840
9 ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$	102.00 ✓	80.80 photo *
10 RADIATOR GRILLE COVER - UPPER		\$	187.00 +	
11 FRONT BUMPER AIR GUIDE GRILLE - LH		\$	468.00 +	
12 FRONT BUMPER CARRIER		\$	795.00 ✓	
13 FRONT BUMPER FOAM FILLER PIECE		\$	123.00 ✓	98.40
14 FRONT BUMPER TOP COVER		\$	126.00 +	
15 CAUTION SIGN STICKER	NEC	\$	14.00 +	
16 AIRCON STICKER	NEC	\$	8.00 +	
17 LOCK CARRIER BRACKET		\$	136.00 +	
18 LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$	56.00 +	
19 FRONT PARKING AID SENSOR - INNER		\$	242.00 +	
20 FRONT PARKING AID SEAL RING	4	\$	14.00 +	

SUB TOTAL SPARE PARTS

\$ 8,304.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 HORN - LH HIGH TONE		\$ 124.00	X
22 SPRING SHACKLE - LH		\$ 29.00	X
23 LED HEADLIGHT - LH		\$ 7,812.00	X
24 LIFT CYLINDER - LH		\$ 196.00	X
25 RADIATOR AIR GUIDE - INNER		\$ 31.00	X 24.64
26 RADIATOR AIR GUIDE - OUTER		\$ 16.00	1
27 FRONT NO PLATE		\$ 60.00	✓
28 SUNDRIES		\$ 300.00	✓ 8.86
TOTAL SPARE PARTS	:	\$ 16,872.00	
TOTAL LABOUR CHARGES	:	\$ 3,272.00	
GRAND TOTAL	:	\$ 20,144.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Adrian L.
: 06/11/20.1

: Not Authorised, 03 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0842/2020/NS
06-Jan-21
CHANG
1 of 1
SMG 8340 A
AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISMANTLE AND RENEW BONNET.	\$ 800.00	\$ 500.00 ✓
2	TO RESPRAY BONNET.	\$ 900.00	\$ 550.00 ✓
			<u>\$ 1,050.00</u>
Parts			
1	BONNET <i>Buckled</i>	\$ 3,312.00	\$ 2,649.60 ✓
2	BONNET IMPACT PROTECTION - CENTER <i>Green</i>	\$ 28.00	\$ 22.00 ✓
3	BONNET IMPACT PROTECTION - LH/RH <i>2</i>	\$ 56.00	\$ 43.68 ✓
4	OUTER TEMPERATURE SENSOR BRACKET <i>could</i>	\$ 19.00	\$ 14.56 ✓
			<u>\$ 2,729.84</u>
GRAND TOTAL		\$ 5,115.00	

For Premium Automobiles Pte Ltd

Adrian S
H/S

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0842/2020/NS
DATE : 04-Nov-20
WIP : 56410

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

*Hi Adrian,**5 days - ok - Jy - 25 Feb 21***ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT****TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR DEBETS FRANK JOZEF CHRISTIAAN
ADDRESS : 1D SHELFORD ROAD
#02-23
SINGAPORE 286889
TELEPHONE : HP +65 97438778
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800152156
VEHICLE NO : **SMG 8340 A**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 31/12/2018
ENGINE NO : CVK 073246
CHASSIS NO : WAUZZZF58KA010127
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 06-Oct-20
PLACE OF ACCIDENT : CORNER OF SHELFORD RD & DUNEARN RD

2.60

1.70

1.60 = \$13.70


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 8340 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER.	\$ 1,000.00	\$ 550.00
5	SUPPLEMENTARY	\$ 1,700.00	\$ 1,050.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,972.00	\$ 2,772.00


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 2,251.00	\$ 1,800.80
2 FRONT BUMPER FIXING PARTS		\$ 402.00	
3 FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4 FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5 FRONTBUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 225.00	
6 FRONT BUMPER SPOILER		\$ 529.00	
7 FRONT BUMPER AIR GUIDE - LH		\$ 62.00	
8 RADIATOR GRILLE		\$ 2,300.00	\$ 1,840.00
9 ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$ 102.00	\$ 80.80
10 RADIATOR GRILLE COVER - UPPER		\$ 187.00	
11 FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 468.00	
12 FRONT BUMPER CARRIER		\$ 795.00	
13 FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	\$ 98.40
14 FRONT BUMPER TOP COVER		\$ 126.00	
15 CAUTION SIGN STICKER	NEC	\$ 14.00	
16 AIRCON STICKER	NEC	\$ 8.00	
17 LOCK CARRIER BRACKET		\$ 136.00	
18 LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$ 56.00	
19 FRONT PARKING AID SENSOR - INNER		\$ 242.00	
20 FRONT PARKING AID SEAL RING	4	\$ 14.00	
SUB TOTAL SPARE PARTS	:	\$ 8,304.00	\$ 3,820.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8340 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 3,820.00
21	HORN - LH HIGH TONE	\$	124.00	
22	SPRING SHACKLE - LH	\$	29.00	
23	LED HEADLIGHT - LH	\$	7,812.00	
24	LIFT CYLINDER - LH	\$	196.00	
25	RADIATOR AIR GUIDE - INNER	\$	31.00	\$ 24.64
26	RADIATOR AIR GUIDE - OUTER	\$	16.00	
27	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
28	SUPPLEMENTARY	\$	3,415.00	\$ 2,729.84
29	SUNDRIES	\$	300.00	\$ 8.96
TOTAL SPARE PARTS		:	\$ 20,287.00	\$ 6,643.44
TOTAL LABOUR CHARGES		:	\$ 4,972.00	\$ 2,772.00
GRAND TOTAL		:	\$ 25,259.00	\$ 9,415.44

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

BL-05/02/21