

ASS. REC. BY:

REF:

Smo/20012223/Kf

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

04/29

Person Contacted:

Vehicle: IN / OUT

M. K.

Veh No:

STQ 4421 J Yr Regn: 05, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed c.c. 1496

Colour

M. Silver AC: Insured / Std / NI / NA

Sp. Reading

14326P T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SRIM / STD A/Rim or

Tyre Size:

F: Kapsen 195/50R15

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

7 mm

L/Bal.

8 mm

L/Bal.

7 mm

D.O.A.

30/10/20

D.O.I.

9/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

Kennoth
96910663

My Tyre Autoservice Pte Ltd
2 Yishun Industrial Street 1
#01-10 Northpoint BizHub
Singapore 768159

Not Notarised
C/P 8
Rummy After Pain
4 days

SJQ4421J Honda Freed

Accident Date: 30/10/2020

No	Qty	Parts Description	Estimated Parts Price	
			B/S	1,207.90 ✓
1	1	Rear bumper assy	S R	125.60 X
2	2	Rear bumper bracket	S S	126.80 X
3	2	Rear bumper retainer	S S	66.30 X
4	1	Rear bumper tow cover	S B	1,857.20 ✓
5	1	Rear tailgate assy	S S	232.80 X
6	1	Rear tailgate inner trim board	S S	274.60 X
7	1	Rear tailgate weatherstrip	S R	188.20 ✓
8	1	Rear tailgate lock mechanism	S R	86.70 X
9	1	Rear tailgate lock catch	S R	161.10 X
10	2	Rear tailgate hinges	S S	271.60 X
11	2	Rear tailgate damper	S S	579.40 X
12	1	Rear tailgate wiper motor	S S	163.30 X
13	1	Rear tailgate wiper blade assy	S CM	240.20 ✓
14	1	Rear tailgate outer garnish	M3 CM	123.50 ✓
15	1	Rear tailgate no plate lamp	S M	68.80 ✓
16	1	Rear tailgate center logo	S R	66.50 ✓
17	1	Rear tailgate 'freed' emblem	S S	680.80 X
18	1	Rear left taillamp	S S	680.80 X
19	1	Rear right taillamp	S R	841.70 X
20	1	Rear end lower panel	S S	129.90 X
21	1	Rear end lower panel top garnish	S M	188.90 ✓
22	1	Rear windscreen glass moulding	S R	1,098.60 X
23	1	Rear exhaust muffler assy	S S	66.00 X
24	2	Rear exhaust muffler rubber mounting	S	9,527.20
			S	1,905.44
		Less 20%	S	7,621.76

Special Nett Items

1	10	Rear bumper clips	S R	50.00 ✓
2	4	Rear tailgate outer garnish clips	S R	20.00 ✓
3	8	Rear tailgate inner trim board clips	S R	30.00 X
4	1	Rear end panel sealant	S R	120.00 X
5	4	Rear end lower panel top garnish clips	S R	20.00 X
6	1	Rear windscreen glass sealant	S R	80.00 4000
7	2	Rear bumper reverse sensor	S SHW	250.00 2005N-
8	1	Rear view camera	S S	300.00 X
9	1	Rear no plate	S R	80.00 455N-
			S	950.00

Total parts

\$ 8,571.76

My Tyre Autoservice Pte Ltd
2 Yishun Industrial Street 1
#01-10 Northpoint BizHub
Singapore 768159

SJQ4421J Honda Freed

Accident Date: 30/10/2020

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,400.00	500l
2	To putty and spray painting rear portion.	\$ 1,400.00	450l
3	To check rear lighting and wiring.	\$ 50.00	20l
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60l
5	To remove and install rear exhaust muffler assy.	nn \$ 120.00	X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ nn 180.00	X
7	To apply anti rust proofing to rear affected area.	\$ 140.00	30l
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50l
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120l
10	To remove and install rear view camera.	\$ 80.00	50l
11	Towing service.	nn \$ 100.00	X
Total labour :		\$ 3,770.00	

Total parts : \$ 8,571.76

Total labour : \$ 3,770.00

Total repair cost : \$ 12,341.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 31/10/2020 09:58
Date Of Accident 30/10/2020 08:50
Exact Location Of Accident PIE TWRDS ECP
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJQ4421J
Insured/Policyholder
Name Of Registered Owner HADI BIN HARON
NRIC No SXXXX540B
Email Address HADIHARON@GMAIL.COM
Mobile Phone No (LOCAL) +65-88682043
Alternative Phone No OTHERS-88682043

Vehicle Particulars

Manufacturer HONDA
Model HONDA / FREED 1.5G A
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5109434250-01
Cover Note Number

Driver

Name of Driver AHMAD SHAFIQ BIN GAZALI
NRIC No SXXXX985I
Date Of Birth 31/03/1982
Occupation OUTDOOR
Date Of Driving Pass 07/02/2012
Driving Experience 8 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92378284
Fax Number
Contact Number
Email Address A.MAD.SHAFIQ@GMAIL.COM

BLK 461 PASIR RIS DRIVE 04 #11-287

510461

Is the Driver an employee of the Insured's Company? NO
Relationship of the Driver with the Insured FRIEND
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED;


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: WITH OWNER/DRIVER
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDE8388E
Vehicle Make/Model/Colour HONDA / FREED 1.5G CVT
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN KUAN SHENG, CEMENT (CHEN GUANSHENG, CLEMENT)
NRIC/Passport Number SXXXX237J
Contact Number
Address 75 JALAN BUMBONG
Postcode 739890
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30 October 2020, I was driving along PIE towards ECP at around 8:50AM, when a Blue SG car ^(SLV 2366Z) sudden lane braked in front of me. I managed to brake in time avoiding a collision but the car behind me, SDE 8388E, didn't stop in time and hit the car I was driving from behind.

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/10/2020 10:15AM

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No: 3 OCT 2020