

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

756-111282-19

INVOICE

To: City Container (S) Pte Ltd
c/o No. 1 Kaki Bukit Avenue 6
#01-49, Autobay
Singapore 417883

Date : 31/10/2019

Invoice No : IV19-10046/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle XD 3722A (TRC 9397S) (Inclusive Of Photographs And Transport Charges) Our reference : CAS/19-10/046	\$1,407.00
Total	\$1,407.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: City Container (S) Pte Ltd
c/o No. 1 Kaki Bukit Avenue 6
#01-49, Autobay
Singapore 417883

Date : 31/10/2019

Reference No : CAS/19-10/046

General Information

Registration No. : XD 3722A (TRC 9397S)
Accident Date : 16/09/2019

Particulars of Damaged Vehicle

Colour	: Blue	Make & Model	: Sin Trans Engrg P L 40' Tri-Axles SKL Container Trailer
Engine Capacity	: 0 cc	Pre-Accident Condition	: Good
Mileage (KM)	: -	Engine No.	: -
Chassis No.	: STEPL288514	Steering	: In Order
Registration Date	: 04/04/2014	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Rear Tyre	295/80R22.5	FIREMAX	60%
L/H Rear Tyre	295/80R22.5	FIREMAX	60%

Inspection

Repairer : YSK Auto Workshop
No. 1 Kaki Bukit Avenue 6, #01-49, Autobay Singapore 417883

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$32,020.00
Revised Amount : \$22,950.00
Less Excess : -
Nett Total : \$22,950.00

Remarks

- (A) Survey was done on 08/10/2019
- (B) Re-survey was done on 10/10/2019
- (C) Re-survey after repair was done on 21/10/2019
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : XD 3722A (TRC 9397S)

Our ref : CAS/19-10/046

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	2pcs	Trailer suspension axle assy (used) No. 1 & 2 @ \$4,500.00	Twisted/Jammed	9,000.00	9,000.00
2	2sets	Trailer suspension leaf springs – No. 1 @ \$850.00	Twisted/Bent	1,700.00	1,700.00
3	2sets	Trailer suspension leaf springs – No. 2 @ \$850.00	Twisted/Bent	1,700.00	1,700.00
4	2pcs	Leaf spring support bracket RH @ \$450.00	Bent	900.00	900.00
5	2pcs	Leaf spring support bracket LH @ \$450.00	Bent	900.00	900.00
6	2pcs	Leaf spring bracket crossmember @ \$550.00	Bent	1,100.00	1,100.00
7	4pcs	Leaf spring bracket lock nuts @ \$280.00	Bent	1,120.00	1,120.00
8	8pcs	Leaf spring 'U' bolt @ \$45.00	Bent	360.00	360.00
9	4pcs	Leaf spring 'U' bolt bracket @ \$65.00	Bent	260.00	260.00
10	4pcs	Axle adjustable control arm @ \$350.00	Bent	1,400.00	1,400.00
11	8pcs	Axle adjustable control arm bolt @ \$45.00	Bent	360.00	360.00
12	16pcs	Axle adjustable control arm bush @ \$35.00	Necessary	560.00	560.00
13	4pcs	Brake air chambers @ \$350.00	2pcs Damaged	1,400.00	700.00
14	4pcs	Brake air chamber hose @ \$60.00	2pcs Damaged	240.00	120.00
15	3pcs	Rear wheel guard RH @ \$220.00	Dented/Broken	660.00	660.00
16	1pc	Rear wheel guard LH	Broken	220.00	220.00
17	4pcs	Rear wheel guard support @ \$60.00	Bent/Twisted	240.00	240.00
18	3pcs	Rear wheel rim RH @ \$800.00	Dented/Warped	2,400.00	2,400.00
19	2pcs	Rear tyre LH @ \$550.00	Grazed/Cut (60%)	1,100.00	660.00
20	1pc	Side protection railing assy RH	Damaged	1,200.00	1,200.00
21	4pcs	Rear tyre RH @ \$550.00	Grazed/Cut (60%)	2,200.00	1,320.00
			Sub total	29,020.00	26,880.00
		<u>LABOUR & MISC. CHARGES</u>			
1		To respray painting & etc		1,200.00	600.00
2		Panel beating, cut, weld, remove & replacing above parts		1,800.00	1,200.00
			Grand total	32,020.00	28,680.00
Recommended cost of lump sum repair (To its pre-accident condition)					22,950.00

Constant Appraiser Services

Vehicle No : XD 3722A (TRC 9397S)

Our ref : CAS/19-10/046


Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$22,950.00** on a contractual basis. Under normal circumstances, the repair period would be about **10 (Ten)** working days.

Yours faithfully,

Constant Appraiser Services

A handwritten signature in black ink, appearing to read 'Lim Yong Tian', is written over a circular stamp. The stamp contains the text 'CONSTANT APPRAISER SERVICES' around the perimeter and 'CAS' in the center.

Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA