FormTeam Consultancy Pte Ltd (Co.Reg.No:200819280D)

33 Ubi Avenue3 #02-15, Vertex
Singapore 408868
Tel: 6509 1788 Fax: 6509 6221 Email: motorsurvey@fta.com.sg

VEHICLE DAMAGE INSPECTION REPORT

Our File No: MSIG19-106438/PRS/SK/ADJ/SK

Date: 26/11/2019

6M70427062

672489 km

FP51JDA00675

REFERENCE

MSIG Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

MSD/VCC/18-001149-00

Engine No:

Chassis No:

Odometer:

Claimant Vehicle

XD3722A

Insured Vehicle No :

XD7658B

Date of Loss:

No:

16/09/2019

Nature of ΤP Claim:

Claim No: MSC/V/19-001126

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD3722A

Make & Model: MITSUBISHI FP51JDR4RDEA, 12.9 D (M) 04/05/2009 (Man. Year: 2009) Reg. Date: Colour: Yellow/Blue

12882 cc

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

295/80 R22.5 Front Tyre Size: 295/80 R22.5 Rear Tyre Size: Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm Rear Right Side: Front Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		26,880.00	12,350.00	14,530.00	54.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,800.00	1,200.00	600.00	33.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	28,680.00	13,550.00	15,130.00	52.75
	Approved Total (Overridden) (S\$)		10,850.00		
	Nett Amount (S\$)	28,680.00	10,850.00	17,830.00	62.17

INSPECTION

Date of Assignment: 23/10/2019

PAPER SURVEY REPORT Date Inspected: 09/10/2019, 21/11/2019 Inspected At: (Repairer: Ysk Auto Workshop)

Estimated Period of Repair: 12.0 days

Adjuster: Manager: Lim Say Koon Frankie

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Nov 2019)

MITSUBISHI FP51JDR4RDEA 12.9 D (M) (Model not available in database) Parts: N/A

(Price-denominated Standard List) Labour: Repairer's

Print Code: FormTeam Consultancy Pte Ltd/XD3722A/26/11/2019 14:23

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRAILER SUSPENSION AXLE ASSY (USED) No 2 Repair/Reuse	No 1 Twisted/Jammed	9,000.00 FS	*4,500.00 FS
2	2		*TRAILER SUSPENSION LEAF SPRINGS (SET)	Twisted/Bent	1,700.00 FS	*1,700.00 FS
3	2		*TRAILER SUSPENSION LEAF SPRINGS (SET)	Reuse	1,700.00 FS	*-FS
4	1		*LEAF SPRING SUPPORT BRACKET RH	No 1 Bent, No 2 Reuse	900.00 FS	*450.00 FS
5	1		*LEAF SPRING SUPPORT BRACKET LH	No 1 Bent, No 2 Reuse	900.00 FS	*450.00 FS
6	1		*LEAF SPRING BRACKET CROSSMEMBER	Bent	1,100.00 FS	*550.00 FS
7	2		*LEAF SPRING BRACKET LOCK NUTS	Bent	1,120.00 FS	*280.00 FS
8	4		*LEAF SPRING U BOLT	Bent	360.00 FS	*180.00 FS
9	2		*LEAF SPRING U BOLT BRACKET	Bent	260.00 FS	*130.00 FS
10	2		*AXLE ADJUSTABLE CONTROL ARM	Bent	1,400.00 FS	*700.00 FS
11	8		*AXLE ADJUSTABLE CONTROL ARM BOLT	Bent	360.00 FS	*180.00 FS
12	16		*AXLE ADJUSTABLE CONTROL ARM BUSH	Necessary	560.00 FS	*280.00 FS
13	2		*BRAKE AIR CHAMBERS	Damaged	700.00 FS	*700.00 FS
14	2		*BRAKE AIR CHAMBERS HOSE	Damaged	120.00 FS	*120.00 FS
15	3		*REAR WHEEL GUARD RH	Dented/Broken	660.00 FS	*660.00 FS
16	1		*REAR WHEEL GUARD LH	Broken	220.00 FS	*220.00 FS
17	2		*REAR WHEEL GUARD SUPPORT	Bent/Twisted	240.00 FS	*120.00 FS
18	1		*REAR WHEEL RIM RH	Dented/Warped	2,400.00 FS	*800.00 FS
19	2		*REAR TYRE LH	Serviceable/Reuse	660.00 FS	*-FS
20	1		*SIDE PROTECTION RAILING ASSY	Repair	1,200.00 FS	*-FS
21	1		*REAR TYRE RH	Grazed/Cut (60%)	1,320.00 FS	*330.00 FS
F=Franchise part. S=SpcNett.				10.070.00		
				Total Parts (S\$)	26,880.00	12,350.00

FormTeam Consultancy Pte Ltd/XD3722A/26/11/2019 14:23. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO RESPRAY PAINTING & ETC.	New	600.00	400.00				
2	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS.	New	1,200.00	800.00				
	Gross Labour Cost (S\$)		1,800.00	1,200.00				

FormTeam Consultancy Pte Ltd/XD3722A/26/11/2019 14:23. Not valid without Reference section.

< END OF ESTIMATES >