



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
KELVIN C.H.I.A PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW20012228/Dqf3e2	
			Date: 15/04/2021	
			Code: L041	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	XD 7658D	Veh. Inspected	TRC 9397S (XD 3722A)	
Policy No.		Coverage (\$)	0.00	
Claim No.	2020001052.MSIG	Excess (\$)	0.00	
Assign From	TEO YI XUAN	Assign Date	07/11/2020	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	STEPL288514	Colour	BLUE	
Odometer	-	Steering		
Brakes		Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5 (D)	FIRENZA	5/5 mm	
L/H Front Tyre	295/80 R22.5 (D)	FIRENZA	5/5 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	FIRENZA	5/5/5/5 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	FIRENZA	5/5/5/5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	16/09/2019	Inspection Date	24/11/2020	
Survey held at	51 GUL DRIVE			
Repairer	YSK AUTO WORKSHOP			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	