

Date : 10-Nov-20

Registration no. : SMV9559B / Mercedes Benz GLC300 2.0 4Matic M-Hybrid A

DOA : 7-Nov-20

Estimate No. : 19A010_SMV9559B_GLC300

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Front door RH ✓ DD	3366.00 2350 ✓
2	1	Front door outer moulding RH × NN	194.00
3	1	Front door inner lock RH × NN	427.00
4	1	Front door weatherstrip inner RH × NN	226.00
5	1	Front door weatherstrip outer RH ✓ NEC	284.00 ✓
6	20	Front door rivet RH @ \$9.00 ✓ NEC	180.00 30 ✓
7	1	Front door ornamental cover RH × NN	139.20 30
8	1	Front door regulator assy RH × NN	829.00
9	1	Door centre pillar outer RH × Repair To repair	0.00
10	1	Rear door RH ✓ DD	3241.00 2550 ✓
11	1	Rear door outer moulding RH × DD	187.00
12	1	Rear door inner lock RH × NN	416.00
13	1	Rear door lock RH ✓ Jammed	427.00 ✓
14	1	Rear door weatherstrip inner RH × NN	226.00
15	1	Rear door weatherstrip outer RH ✓ NEC	284.00 ✓
16	2	Rear door hinges RH @ \$108.00 ✓ BT	216.00 ✓
17	1	Rear door checker RH × NN	173.00
18	1	Rear door trimboard RH ✓ BR	872.00 650 ✓
19	1	Rear door regulator assy RH × NN	824.00
20	20	Rear door rivet RH @ \$9.00 ✓ NEC	180.00 30 ✓
21	1	Rear door ornamental cover RH × NN	139.20
22	1	Rear shock absorber RH × NN	488.00
23	1	Rear lower arm RH × NN	589.00
24	1	Rear upper arm RH × NN	492.00
25	1	Rear trailing arm RH × NN	395.00
26	1	Rear knuckle arm RH ✓ BT	924.00 821 ✓
27	1	Rear knuckle arm bearing RH ✓ Jammed	435.00 399 ✓
28	1	Rear fender RH × Repair To repair	0.00
29	1	Rear wheel arch garnish RH ✓ CRU	382.00 ✓
			16535.40

Less 10% 8423
-10%
7580.70

1653.54
14881.86

Date : 10-Nov-20

Registration no. : SMV9559B / Mercedes Benz GLC300 2.0 4Matic M-Hybrid A

DOA : 7-Nov-20

Estimate No. : 19A010_SMV9559B_GLC300

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries ✓ NEC	60.00 30✓
2	1set	Front door trimboard clips ✓ NEC	45.00 30 20 ✓
3	1	Front door sealant ✓ NEC	100.00
4	1set	Rear door trimboard clips RH ✓ NEC	45.00 30 20 ✓
5	1	Rear door sealant RH ✓ NEC	100.00
6	1set	Rocker garnish clips RH ✓ NEC	100.00 30 20 ✓
7	1set	Rear fender inner shield clips RH × NN	30.00
8	1set	Rear wheel arch garnish clips RH ✓ NEC	80.00 30 20 ✓
9	1	Rear alloy rim RH ✓ CUT	980.00 ✓
10	1	Rear tyre RH × NN	260.00
			1800.00
Parts Total			16681.86
			1090

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1200.00 800
2	1	Check wiring system after disconnect and connect.	80.00 50
3	1	R&R interior upholstery.	200.00 ×
4	1	R&R RH front door component.	80.00 50
5	1	R&R RH rear door component.	80.00 50
6	1	R&R RH rear tyre and balancing.	60.00 30
7	1	R&R RH rear undercarriage component.	300.00 200
8	1	To conduct all wheel alignment.	150.00 60
9	1	To apply undercoating for rust roofing.	200.00 30
10	1	Spray painting on accident area.	1500.00 920
Labour Total			3850.00
			2190

Total Parts and Labour Cost of Repair

20531.86

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Steve (LKK)
 Without Prejudice
 9/11/20
 L/S
 Resurvey After Spray
 5 repair days

P - 7580.90
 N- 1090
 L - 2190
 10,860.90
 L/S - 8688.72
 = 8700