

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: *MC* Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Falken*

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: *dp* / *o/s* / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

have video. LTA # 37968
Damage consistent (front bumper black mark is taxi tyre mark.
17/11/20 L/S # 4000 confirmed with Alan.

MM Tasper

Not Authorised
Date
9/11/20
2/58 4000/
4 days!

"CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: SKX 3227L

1PC	FRONT BUMPER	DD	762.30	\$988.20
1PC	FRONT BUMPER FOG LAMP O/S	CNA	380.50	\$485.50
1PC	FRONT BUMPER FOG LAMP COVER O/S	Int	185.20	\$166.30
1PC	FRONT BUMPER REINFORCEMENT	Bnf	371.30	\$391.20
1PC	FRONT BUMPER SIDE RETAINER O/S	Bnf	41.50	\$65.50
1PC	FRONT BUMPER LOWER SPOILER	DS	488.20	\$650.50
1SET	FRONT BUMPER CLIPS	NA		\$50.00
1PC	FRONT GRILLE	CNA	542.20	\$615.20
1PC	HEADLAMP O/S	CNA	1859.10	\$1,939.20
1PC	FRONT FENDER O/S	R		\$671.10 X
1PC	FRONT FENDER INNER SHIELD O/S	17		\$215.30 X
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	NA		\$50.00 X
1PC	FRONT FENDER OUTER PROTECTOR O/S	DS	245.50	\$282.30
1PC	FRONT SPORT RIM O/S	R		\$850.00 X
1PC	FRONT LOWER ARM O/S	17		17 \$488.20 X
1PC	FRONT KNUCKLE ARM O/S	17		17 \$455.30 X
1PC	FRONT KNUCKLE ARK BEARING O/S	17		17 \$250.50 X
1PC	FRONT SHOCK ABSORBER O/S	17		17 \$415.20 X
				\$9,029.50

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REPLACED FRT UNDER CARRIAGE
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 20
17 \$80.00 X
\$150.00 60
17 \$180.00 X
17 \$120.00 X
\$800.00 400
\$1,200.00 600
TOTAL \$11,639.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4905 80
202
392464
5004.64
202
4003