

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC6/A16200/2241/4693

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M/

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*have car**acc 6-2-2022 MA 6253**BI involved. Note 3742**17/11/20 4/5 @ 3300 confirmed with Alan*

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

)

FASTTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorised
done
for S. 1/5 @ 3300
9/11/20

VEHICLE No.SGR 3721E

1PC	BOOTLID		1	\$766.50	X
1PC	BOOTLID OUTER HANDLE		11	\$198.10	X
1PC	BOOTLID REAR LOGO		11	\$60.80	—
1PC	BOOTLID 'VIOS' EMBLEM		11	\$55.20	—
1PC	BOOTLID 'E' EMBLEM		11	\$48.80	X
1PC	BOOTLID 'TRD' EMBLEM		11	\$65.00	—
1PC	BOOTLID INNER LOCK		11	\$199.40	X
1PC	BOOTLID LOCK STRIKER		11	\$89.90	X
1PC	BOOTLID WEATHERSTRIP	245.50	11	\$266.50	—
2PCS	BOOTLID HINGES @\$150.00		11	\$300.00	X
1PC	REAR BUMPER	366.30	11	\$655.10	—
2PCS	REAR BUMPER SIDE RETAINERS @\$76.50		11	\$153.00	X
2PCS	REAR BUMPER BRACKETS @\$99.10		11	\$198.20	X
1PC	REAR BUMPER LOWER SKIRTING		11	\$850.00	X
2PCS	REAR BUMPER REFLECTORS @\$195.00		11	\$390.00	X
1SET	REAR BUMPER CLIPS		11	\$50.00	—
1PC	REAR EXHAUST		11	\$588.10	X
2PCS	REAR EXHAUST MOUNTINGS @\$65.00		11	\$130.00	X
1PC	REAR END PANEL	581.23	11	\$655.20	—
1PC	REAR END PANEL GARNISH	188.20	11	\$315.10	—
2PCS	TAILLAMPS @\$520.10	425.30 x 2 = 850.60	11	\$1,040.20	—
2PCS	TAILLAMPS HOUSING PANELS @\$199.50		11	\$399.00	X
1PC	REAR FLOOR PANEL		11	\$911.20	X
1PC	REAR FLOOR PANEL TOP BOARD		11	\$422.50	X
2PCS	REAR FLOOR PANEL SIDE TOOLS SPONGES @\$389.10		11	\$778.20	X
2PCS	REAR FENDERS @\$845.10		11	\$1,690.20	X
2PCS	REAR FENDER INNER TRIMS @ \$286.50		11	\$573.00	X
2PCS	REAR FENDER INNER SPLASH SHIELDS @\$105.00		11	\$210.00	X
1PC	REAR WINDSCREEN MOULDING		11	\$66.80	X
				\$12,126.00	

(252)

1SET	S.NETT		should	\$280.00	200
1PC	REAR BUMPER REVERSE SENSOR		11	\$50.00	✓
1PC	REAR END PANEL SEALANT		11	\$200.00	X
1PC	REAR FLOOR PANEL INSULATOR		11	\$50.00	X
1PC	REAR WINDSCREEN SEALANT		11	\$80.00	X
1PC	REAR EXHAUST CHROME		11	\$680.00	X
1PC	BOOTLID TOP SPOILER				

TO CHECK WIRING

\$80.00 30

TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	11 \$80.00	X
TO SPRAY RUST PROOFING	\$120.00	30
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO DISMANTIE & REFIX CUSHION UPHOLSTERY	\$180.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO DISMANTLE & REFIX FUEL TANK	11 \$100.00	X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	800
TO PUTTY & SPRAY PAINTING	\$1,680.00	1080
TOTAL	\$17,836.00	

UKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-246283
252
1847.12
4167.12
3333