

Stenc CLKK)
w/ ML

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

9/11/20, 3:00pm

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

3 days
Ry AL SPY

ESTIMATE OF REPAIR

Veh# : GBE1890B

Model: CITROEN BERLINGO
(15/7/2011)

Accident Date : 6/11/2020

Location : CTE TOWARDS AYE BEFORE ANG MO KIO AVE 1 EXIT

3P: GBE73775 (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper / DLT	631.80	-	-
2	10pcs	Rear bumper clips / 1PC	-	30.00	-
3	2pcs	Rear bumper screw clips X	-	20.00	-
4	1pc	Rear bumper enforcement 1 / BT	347.10	-	-
5	2pcs	Rear bumper o/s & n/s retainer / DR	166.20	-	-
6	1 pc	Rear end panel X R	1,283.10	-	-
7	2pcs	Rear reverse sensor / Shorted	-	380.00	200
8	2pcs	Rear reverse sensor wire harness X	-	180.00	-
9	1pc	Rear o/s & n/s door (repair) X Repair	-	-	-
10	1pc	Rear door weatherstrip X	180.00	-	-
11	1pc	Rear door 'CITROEN' emblem X / 1PC	86.50	-	-
12	1pc	Rear door 'BERLINGO' emblem X / 1PC	88.60	-	-
13	1pc	Rear door 'C&C' emblem X / 1PC	65.60	-	-
Sub-Total:			2,848.90	610.00	0.00
			10%	0%	10%
After Less %:			2,564.01	610.00	0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	1,200.00	250	300
2		To spray painting.	1,000.00	300	
3		To check wiring.	100.00	30	
4		To re-seal anti-rust.	80.00	X	
Sub-Total:			2,380.00		
Total:			5,554.01		
After Less 20%:			4,443.21		

Man

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bisSAFE 8778 1999
24 hr accident call

Mobil 1



GBE1890B ESTIMATEPg1