

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20012245/KQD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/20-409093-CA
Claimant Vehicle No :	SDH6777M	Insured Vehicle No :	FBJ3508G
Date of Loss:	08/11/2020	Nature of Claim:	TP
		Claim No:	MSC/V/20-000811

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH6777M	Engine No:	L15B3508712
Make & Model:	HONDA VEZEL, 1.5 G (A)	Chassis No:	RU11008697
Reg. Date:	17/10/2014 (Man. Year: 2014)	Odometer:	110627 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,900.08	2,509.68	390.40	13.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	1,330.00	240.00	15.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,470.08	3,839.68	630.40	14.10
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	4,470.08	3,250.00	1,220.08	27.29
+ GST 7.00/7.00% (S\$)	312.91	227.50	85.41	27.30
Nett Amount (S\$)	4,782.99	3,477.50	1,305.49	27.29

INSPECTION

Date of Assignment:	10/11/2020	
Date Inspected:	09/11/2020	Inspected At:
		CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2021)
Parts:	144	HONDA VEZEL 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH6777M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	508.50 FL	*508.50 FL
2	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
3	1		*REAR TAILGATE	Bent	1,100.90 FL	*953.00 FL
4	1		*TAILGATE EMBLEM (VEZEL)	Necessary	43.50 FL	*43.50 FL
5	1		*REAR SPARE TYRE PANEL UNDER COVER	Repair	190.00 FL	*- FL
6	1		*REAR WINDSCREEN GLASS	Shattered	1,350.10 FL	*1,200.00 FL
7	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	108.70 FL	*108.70 FL
8	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
9	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,565.10	3,077.10
- List Item Discount on L Items 20.00/20.00% (\$)	665.02	567.42
Total Parts (\$)	2,900.08	2,509.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, THIRD BRAKE LIGHT, SPOILER ASSY, KNOCK & REPAIR REAR END PANEL & REALIGN THE SAME	New	600.00	450.00
3	PUTTY & RESPRAY ON REAR PANEL, TAILGATE, REAR GARNISH, REAR SPARE TYRE PANEL	New	600.00	550.00
4	REMOVE & REFIX REAR SEAT, CARPET, GARNISH, WASH CUSHION	New	120.00	80.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
6	RUSTPROOFING	New	30.00	30.00
7	TOWING	New	50.00	50.00
Gross Labour Cost (\$\$)			1,570.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >