

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 23 Nov 2020

Preliminary Advice

Insured Vehicle No	: FBJ3508G	Accident Date	: 08/11/2020
TP Vehicle No	: SDH6777M	Assignment Date	: 10/11/2020
Make	: HONDA VEZEL	Est. Duration of Repair	: 4
Date of Inspection	: 09/11/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,420.08
Revised Amount	:S\$	3,948.08
Check Items (Estimated)	:S\$	272.00
Total	:S\$	4,220.08
 Lump Sum Repair	 :S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.