

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT

#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg.: 200800062E GST Reg. No.: 200800062E

SCQ 3212
Pcmts

Lexus ES250

List Price \$
Lexus 10%

Rear fender RH Rx

1519.30

Taillamp RH can✓

703.30 727.60

Rear Bumper de✓

989 1015.30

Rear Bumper side retainer RH de✓ ~~nn~~

Reverse PDC sensor x 2 pc/lpcn✓

190 380 x 2

Rear Bumper reflector RH can✓

✓ 189.20

Rear Bumper inner trim ~~nn~~

Rear Bumper reinforcement Beam ~~nn~~ 789.10

Rear Bumper bracket RH ~~nn~~

Boot weather strip x ~~nn~~

rear end panel for garnish x ~~nn~~

Boot lid reflector RH ~~nn~~ 2071.50

Rear exhaust muffler RH ~~nn~~ ↓

10% - 1864.35

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT

#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8716

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg.:200800062E GST Reg. No.:200800062E

SCQ 3212

Lexus ES250

Labour charges

1) To Renew damaged parts &
repair accident area.

700

\$1000

2) To spray paint Bashed,
rear fender, Rear Bumper &
Rear end panel

800

\$1000

3) To check & scan with Lexus
diagnostic computer.

150

\$250

1650

Tanpin 97495749 / 67418439

Ex: tba

5 days

Tanpin @ lkkauto.com.

Not Authorised.

Resurvey check items

Resurvey before/after paint

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT

#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8716

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg. 200800062E GST Reg. No. 200800062E

SCQ 3212

Lexus ES250

Supplementary part

tailamp Lower bracket RH / LH 85.60

Blind spot monitor RH ~~mm~~ ~~2444~~ remove

Rear fender sticker RH / LH 45

Supplementary Labor

To perform rear right blind spot radar \$600
calibration and target aiming. ~~X~~

10% 130.60
10% 117.54

mm
1864.35

1650
117.54

\$3631.89
• 6 days #