

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCQ 321Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,519.30	-
1	TAILLAMP RH	CRACKED	727.60	703.30
1	REAR BUMPER	DEFORMED	1,015.30	989.00
1	REAR BUMPER SIDE RETAINER RH (NPA)	NOT NECESSARY	-	-
2	REVERSE PDC SENSOR @\$380.00	NOT WORKING	760.00	190.00
1	REAR BUMPER REFLECTOR RH	CRACKED	189.20	189.20
1	REAR BUMPER INNER TRIM (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT BEAM	NOT NECESSARY	789.10	-
1	REAR BUMPER BRACKET RH (NPA)	NOT NECESSARY	-	-
1	BOOT WEATHERSTRIP (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL TOP GARNISH (NPA)	NOT NECESSARY	-	-
1	BOOTLID REFLECTOR RH (NPA)	NOT NECESSARY	-	-
1	REAR EXHAUST MUFFLER RH (NPA)	NOT NECESSARY	-	-
1	TAILLAMP LOWER BRACKET RH (ADDITIONAL)	BROKEN	85.60	85.60
1	BLIND SPOT MONITOR RH (ADDITIONAL)	NOT NECESSARY	2,444.00	-
1	REAR FENDER STICKER RH (ADDITIONAL)	NECESSARY	45.00	45.00
	LESS 10% DISCOUNT		-	-220.21
			7,575.10	1,981.89
	LABOUR			
	TO RENEW DAMAGED PARTS & REPAIR ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,000.00	700.00
	TO SPRAY PAINT BOOTLID, REAR FENDER, REAR BUMPER & REAR END PANEL.		1,000.00	800.00
	TO CHECK & SCAN WITH LEXUS DIAGNOSTIC COMPUTER.		250.00	150.00
	TO PERFORM REAR RIGHT BLIND SPOT CALIBRATION AND TARGET AIMING. (ADDITIONAL)	NOT NECESSARY	600.00	-
			2,850.00	1,650.00
	GRAND TOTAL		10,425.10	3,631.89

Report Ref No. CS/FCI20012250/T1td3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		3,631.89
LESS EXCESS		-750.00
NETT LIABILITY		2,881.89

Report Ref No. CS/FCI20012250/T1td3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.