

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPPOINT
#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg.: 200800062E GST Reg. No.: 200800062E

SCQ 3212
Paints

Lexus ES250

List Price \$
Lexus 10%

Rear fender RH Rx

1519.30

Taillamp RH can✓

727.60

Rear Bumper de✓

1015.30

Rear Bumper side retainer RH de✓

Reverse PDC sensor x 2 pc 1 pc can✓

380 x 2

Rear Bumper reflector RH can✓

189.20

Rear Bumper inner trim ?

Rear Bumper reinforcement Beam ?

789.10

Rear Bumper bracket RH ?

Boot weather strip x

rear end panel toy gamish x

Boot lid reflector RH ?

Rear exhaust muffler RH ?

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT

#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg.:200800062E GST Reg. No.:200800062E

SCQ 3212

Lexus ES250

Labour charges

1) To Renew damaged parts & repair accident area.

700

\$1000

2) To spray paint Burred, rear fender, Rear Bumper & Rear end panel

800

\$1000

3) To check & scan with Lexus Diagnostic Computer.

150

\$250

Tanfah 97495449/67418439

Ex: tba

5 days

Tanfah @ lkkauto.com

Not Authorised.

Resurvey check items

Resurvey before/after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: