

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
#04-07-16 SINGAPORE 568047
Tel: 6481 2025 / 6481 5797 Fax No: 6481 8715
Email: service@riverviewauto.com.sg
Website: www.riverviewauto.com.sg
Co. Reg: 200800062E GST Reg. No: 200800062E

SCQ 3212

Lexus ES250

Supplementary part

tailamp Lower bracket RH / LH 85.60
Blind spot monitor RH ~~mm~~ ~~2444~~ ^{remove}
Rear fender sticker RH / ~~mm~~ 45

Supplementary Labor

To perform rear right blind spot radar
calibration and target aiming. X? \$600

nn
1864.35

1650
117.54

\$3631.89
• 6 days #