

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199
ATTN: Motor Claim Department

FAX: 6725 0853

Xiao Chen.

Estimate No: EST2000253
Date: 09 Nov 2020

Veh Reg No: SKE2486L
Make/Model: TOYOTA VIOS E
MANUAL NCP93

Chasis No: MR053HY9305286124

Reg. Date:
Your Ref No: SKC1343H

Claim Type: Third Party
Accident Date: 06/11/2020
TP Veh Reg No: SKC1343H

Estimate Repair Cost to Vehicle No :SKE2486L

Quantity	Description	List Price S\$	Amount S\$
List Price			
1	1 PC FRT FENDER LH <i>Distorted</i>	530.10 ✓	
2	1 PC FRT FENDER COWLING LH <i>torn</i>	148.90 ✓	
3	1 PC FRT LH FENDER VTI" EMBLEM <i>new</i>	46.30 ✓	
4	1 PC FRT LH WHEEL HOUSING <i>Regis</i>	494.10 +	
5	1 PC HEADLAMP LH <i>Cracked</i>	525.30 ✓	
6	1 PC HEADLAMP PANEL LH <i>new</i>	75.50 +	
7	1 PC FRT FENDER ANGLE GARNISH LH <i>new</i>	49.60 +	
8	1 PC FRT SUPPORT PANEL <i>Regis</i>	788.60 +	
9	1 PC FRT BUMPER <i>Distorted</i>	487.30 ✓	
10	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	372.10 ✓	
11	2 PCS FRT BUMPER BRACKET <i>LH Best</i>	342.80 ✓	171.40
12	2 PCS FRT BUMPER SIDE RETAINER <i>Rt Dmgd</i>	109.60 ✓	54.80
13	1 PC FRT FOG LAMP COVER LH <i>Distorted</i>	91.60 ✓	
14	1 PC FRT BUMPER LOGO <i>new</i>	50.80 ✓	
15	1 PC FRT DOOR PROTECTOR LH <i>new</i>	100.70 +	
16	1 PC FRT DOOR PROTECTOR & MOULDING LH <i>new</i>	20.50 +	
17	1 PC FRT AIR CLEANER BOX ASSY <i>Cracked</i>	822.10 ✓	
18	1 PC FRT SHOCK ABSORBER LH <i>Best</i>	352.50 ✓	
19	1 PC FRT SHOCK ABSORBER MOUNTING LH <i>new</i>	157.70 ✓	
20	1 PC FRT KNUCKLE ARM LH <i>Dmgd</i>	442.60 ✓	
21	1 PC FRT BEARING LH <i>Dmgd</i>	127.90 ✓	
22	1 PC FRT WHEEL HUB LH <i>Dmgd</i>	290.70 ✓	
23	1 PC FRT LOWER ARM LH <i>Best</i>	792.30 ✓	
24	1 PC FRT CROSSMEMBER <i>Best</i>	1,552.90 ✓	
25	1 PC FRT DRIVE SHAFT LH <i>Best Dmgd</i>	1,463.70 ✓	
26	1 PC ANTI ROLL BAR <i>Best</i>	368.10 ✓	
27	1 PC ANTI ROLL BAR LINK <i>Best</i>	156.10 ✓	
28	1 PC STEERING RACK & PINION <i>new</i>	1,373.10 +	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Estimate No: **EST2000253**

Date: 09 Nov 2020

Veh Reg No: **SKE2486L**

Make/Model: TOYOTA VIOS E
MANUAL NCP93

Chasis No: MR053HY9305286124

Reg. Date:

Your Ref No: SKC1343H

Claim Type: Third Party

Accident Date: 06/11/2020

TP Veh Reg No: SKC1343H

Estimate Repair Cost to Vehicle No :SKE2486L

Quantity	Description	List Price SS	Amount SS
		12.133.50	
	8848.30 6636.22 Less 25%	3.033.38	9.100.23
	Special Net		
29	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	60.00 <i>30</i>	
30	2 PCS "L" PLATE BRACKET <i>new</i>	70.00	
31	1 PC FRT DOOR STICKER <i>new</i>	250.00	
32	1 PC FRT SPORTS RIM LH <i>at</i>	850.00 <i>400</i>	
33	1 PC FRT TYRE LH <i>Punctured</i>	380.00 <i>180</i>	
		1.610.00	1.610.00
	Labour		
34	1 TO CHECK WIRING	50.00 <i>30</i>	
35	1 TO REFILL AIRCON GAS	120.00 <i>x</i>	
36	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00 <i>300</i>	
37	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>80</i>	
38	1 TO SPRAY UNDERSEAL	100.00 <i>50</i>	
39	1 (REAR) TO SPRAY PAINTING	1,400.00 <i>600</i>	
40	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 <i>800</i>	
		3.870.00	3.870.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 06/11/2020
TP Veh Reg No: SKC1343H

Estimate No: EST2000253
Date: 09 Nov 2020

Veh Reg No: SKE2486L
Make/Model: TOYOTA VIOS E
MANUAL NCP93
Chasis No: MR053HY9305286124
Reg. Date:
Your Ref No: SKC1343H

Estimate Repair Cost to Vehicle No :SKE2486L

Quantity	Description	List Price	Amount
		SS	SS
		Total	SS 14,580.23
		Add GST @ 7%	1,020.62
		Total Amount Payable	SS 15,600.85

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND SIX HUNDRED AND CENTS EIGHTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian G
1/5 10/11/20

07 Days

total: 9226.22

1/5: 7.5K

(Nett Value)

07 Days

7.5K