

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

07-11-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chinn
Denise

Accident date: 06-11-2020

Estimated repair cost for vehicle no: SMF9471D SKODA OCTAVIA

CHASSIS: TMBBP7NE8J0320654

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Dashboard <i>Not New</i>		\$3,080.00 X
1	1	Front Windscreen Moulding <i>Not New</i>		\$200.00 X
1	1	Front L/H Fender <i>Distorted</i>		\$1,055.00 950
2	1	Front L/H Fender Inner Sponge <i>could</i>		\$300.00 55
3	1	Front L/H Fender Cowling <i>tom</i>		\$150.00
4	6	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$39.00
5	1	Front L/H Rim <i>ut</i>		\$1,650.00 1600 (SW)
6	1	Front L/H Tyre <i>Not New</i>		\$450.00 X
7	1	Front L/H Lower Arm <i>Best</i>		\$650.00 580
8	1	Front L/H Knuckle Arm <i>Best</i>		\$780.00
9	1	Front L/H Knuckle Arm Bearing <i>Best</i>		\$620.00 420
10	1	Front L/H Shock Absorber <i>Best</i>		\$810.00 650
11	1	Front L/H Drive Shaft <i>Not New</i>		\$1,860.00 X
12	1	Front Steering Rack <i>Best</i>		\$3,930.00 2950
13	1	Front L/H Side Mirror Assy <i>ut</i>		\$1,300.00
14	1	Front L/H Door <i>Distorted</i>		\$2,300.00 2950
15	2	Front L/H Door Hinge <i>Lower Best</i>	\$350.00	\$700.00 180
16	1	Front L/H Door Outer Handle <i>3x4</i>		\$390.00 X
17	1	Front L/H Door Outer Handle Cover <i>1m</i>		\$190.00 X
18	2	Front L/H Door Frame Sticker <i>New</i>	\$180.00	\$360.00 80 (SW)
19	1	Front L/H Door Chrome Moulding <i>3x4</i>		\$400.00 X
20	1	Front L/H Door Inner Lock		\$740.00 X
21	1	Front L/H Door Weatherstrip <i>new</i>		\$590.00 365
22	1	Front L/H Door Inner Trim Board <i>could</i>		\$955.00 880
23	10	Front L/H Door Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00 30
24	1	Front L/H Door Window Regulator & Motor Assy <i>Not New</i>		\$1,080.00 X
25	1	Front L/H Door Pillar <i>Dented</i>		\$1,210.00 980

26	1	L/H Rocker Panel	Dented	\$1,330.00 880
----	---	------------------	--------	---------------------------

Subtotal:- \$27,184.00

13309

11978.10

SN: 1080

Labour charges

To remove & refit front windscreen	\$120.00 X
Gum	\$50.00 X
To remove & refit dashboard	\$550.00 X
To remove & refit front L/H door, glass, lock, rubber, sticker, gear motor & trim board	\$280.00 80
To remove & refit front undercarriage, drive shaft & steering rack	\$450.00 320
To check wheel alignment	\$150.00 80
To check wiring	\$150.00 30
Tuff kote	\$200.00 100
Towing fee	\$150.00 60
Panel beating	\$2,200.00 1100
Spray painting	\$2,000.00 800

Subtotal:- \$6,300.00

Total:- \$33,484.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 15628.10

L/S: 12.5k

10 Days

12.5k

10 Day.