

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2
SINGAPORE 486443

Steve (LKK)

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-Nov-20

10/11/20, 10.10am

L/S, By AL spm, 4 days

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6486 G

1 pc	End panel	1 / 00	\$	250.00 /
1 pc	End panel inner garnish	1 X M/M	\$	74.00 X
1 pc	Rear bumper	1 / 00	\$	696.00 /
1 pc	Rear bumper lower cover	1 / M/M	\$	206.00 /
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	1 / BR	\$	58.00 /
1 pc	Rear bumper inner sponge	1 X M/M	\$	114.00 X
1 pc	Rear bumper reinforcement	1 / BR	\$	607.00 /
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	1 / BR	\$	108.00 /
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	1 / BT	\$	36.00 /
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	1 / BT	\$	36.00 /
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	1 X M/M	\$	92.00 X
1 pc	Spray tyre clamp	1 X M/M	\$	6.00 X
			\$	2,283.00
			\$	228.30
			\$	2,054.70

1997
-10%
1797.30

Less
10%

S/NETT

1 set	Rear bumper clips	1 / M/M	\$	48.00 30
1 set	End panel inner garnish clips	1 X M/M	\$	30.00 X
1 set	Bootlid stickers	1 / M/M	\$	100.00 80
1 set	Reverse sensor	1 / Shaded	\$	280.00 200
1 pc	Rear bumper protector	1 X	\$	80.00 X
			\$	50.00 30
Sundry			\$	120.00 30
To dismantle / replace reverse sensor to new bumper and reset to the same			\$	180.00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$	1,100.00 600
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the bootlid, floor board panel etc			\$	1,000.00 600
To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid, floorboard panel			\$	200.00 30
To apply rustproofing on the repaired and replaced panels.			\$	5,242.70

P-1797.30

M-310

L-1290

3397.30

L/S-2777.54

=2700

1290