

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

Steve (LKK)

WHL AL

10/11/10, 10.30 am

9-Nov-20

L/S, By AL SPY, 4 days

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6486 G

1 pc	End panel ?	\$ 250.00
1 pc	End panel inner garnish ?	\$ 74.00
1 pc	Rear bumper / DD	\$ 696.00
1 pc	Rear bumper lower cover / CVT	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 / BR	\$ 58.00
1 pc	Rear bumper inner sponge ?	\$ 114.00
1 pc	Rear bumper reinforcement / DR	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 X	\$ 92.00
1 pc	Spray tyre clamp X	\$ 6.00
		\$ 2,283.00
Less 10%		\$ 228.30
		\$ 2,054.70

S/NETT

1 set	Rear bumper clips / MC	\$ 48.00 30
1 set	End panel inner garnish clips ?	\$ 30.00
1 set	Bootlid stickers / MC	\$ 100.00
1 set	Reverse sensor / Shoked	\$ 280.00
1 pc	Rear bumper protector X	\$ 80.00
Sundry		\$ 50.00 30
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the bootlid, floor board panel etc		\$ 1,100.00 600
To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid, floorboard panel		\$ 1,000.00 600
To apply rustproofing on the repaired and replaced panels.		\$ 200.00 30
		\$ 5,242.70

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: