

Section A - Accident Details

Registration Number	SHB5905B
Case Reference Number	TAX/11/20/2010
Registration Date	12/12/2019
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	FONG SOON KIANG
Type of Accident	Side Swipe
Accident Date and Time	5/11/2020 3:00 PM
Accident Reported Date and Time	5/11/2020 4:02 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108724
Special Instruction to ARC, if any	LEFT FRONT PORTION
Prepared Date and Time	6/11/2020 8:47 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$3,121.72	\$537.23
Total Other Cost	\$580.00	\$40.00
TOTAL COST	\$4,975.72	\$1,227.23 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	06/11/2020 9:04 AM	06/11/2020 3:30 PM
Signature		
Remarks		P/P, before paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0215	Invoice Number	
Quotation Date	18.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$580.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace
		53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$977.80	100.00	\$0.00	Replace	Repair
		52421-47030	PAD, FRONT BUMPER (NO.1)	1.00	\$40.70	25.00	\$30.53	Replace	Replace
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given
		52713-47040	MOULDING, FRONT BUMPER SIDE, LH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$10.00	25.00	\$75.00	Replace	Replace
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace
Total					\$4,030.04		\$537.23		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

537.23
+ 200.00
+ 490.00
1227.23
P/P
2 days

SUC
NEC
NEC
SUC
SUC
SUC
NEC
Cut