

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 28B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WHEEL PANEL RH (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	MID TOP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	8,631.50	-
1	MID TOP PANEL WINDSCREEN NOS 1 RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,655.20	-
1	LUGGAGE COMPARTMENT PANEL NOS 1 RH (CONSISTENT)	CRUMPLED	5,603.80	3,200.00
1	REAR WHEEL PANEL RH (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR WHEEL PANEL SIGNAL LAMP (CONSISTENT)	CRUMPLED	186.50	186.50
1	REAR LUGGAGE COMPARTMENT PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-903.85	-
	LESS 15% DISCOUNT		-	-507.98
			17,173.15	2,878.52
	SPECIAL NETT ITEMS			
1	REAR RIM COVER (SN)(CONSISTENT)	SERVICEABLE	200.00	-
5	MID TOP PANEL WINDSCREEN NOS 1 RH SEALANT @ \$50.00 (SN)(CONSISTENT)	SERVICEABLE	250.00	-
1	COMPANY LOGO (SN)(CONSISTENT)	BURST	150.00	150.00
			600.00	150.00
	<u>LABOUR</u>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT WHEEL PANEL RH,MID TOP PANEL RH ,MID TOP PANEL WINDSCREEN NOS 1 RH ,REAR WHEEL PANEL RH AND REAR LUGGAGE COMPARTMENT PANEL .		3,200.00	1,500.00
	SPRAY PAINTING ON AFFECTED AREA FOR 3 COLOURS (8PANELS).		3,600.00	1,600.00
	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS.		1,600.00	100.00
	R/R MID ROW SEAT & TRIM TO FACILIDATE REPAIR.	NOT NECESSARY	1,000.00	-
			9,400.00	3,200.00
	GRAND TOTAL		27,173.15	6,228.52

Report Ref No. CC4/ASM20012279/Qea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM20012279/Qea3q2

0

OI SUN PIN

Asst. Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor