

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : LONPAC INSURANCE BHD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTMG/TP/2011/001
Policy No:	5116758158	Date of Loss:	04/11/2020
Vehicle Reg. No.:	GBK2932R	Driveable?	no
Driver Age:	13/10/1981	Third Party Vehicle No.:	YN185E
Any Injuries?	no	Contact No:	63052788
Insured/Claimant:	SEMBCORP SPECIALISED CONSTRUCTION PTE LTD	Driver:	FOO SIANG HAI (FU XIANGHAI)
Make/Model:	Toyota, Hilux	Vehicle Reg. Date:	19/03/2020
Vehicle Colour:	Silver	Engine Number:	2GDC580157
Chassis No:	MR0CB8DD100502942	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	
Description of Accident/loss	COLLISION - HEAD TO REAR		
Remarks:			
Present Location:	Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG		
COST OF CLAIMS			Amount
Parts			1,460.22
Miscellaneous Items			220.00
Labour			710.00
Paintwork Labour			0.00
Towing			0.00
Gross Total(\$\$):			2,390.22
GST 7.00%(\$\$):			167.32
Nett Amount(\$\$):			2,557.54

This claim is handled by: Lai Yee Meng

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR SIDE BUMPER STEP GARNISH LH cut	148.20	-10.00	133.38
2	1	REAR SIDE BUMPER LH (CHROME) pb	331.40	-25.00	248.55
3	1	REAR SIDE BUMPER BRACKET LH ?	154.20	-10.00	138.78
4	1	REAR BUMPER STEP GARNISH CENTER CRM	287.70	-10.00	258.93
5	1	REAR BUMPER STEP GARNISH INNER PANEL X	756.20	-10.00	680.58
6	1	REAR Side bumper RH (CHROME) pb	331.40	-25.00	248.55
Total Parts (S\$)					1,460.22

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER REVERSE SENSOR X pb	220.00	0.00	220.00
Sub Total (S\$)					220.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 30
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	0.00	600.00 300
Gross Labour Cost (S\$)					710.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
Gross Labour Cost (S\$)					0.00

< END OF ESTIMATES >

PP

before paint phot

Repair day - 2 days.

Sun Prince

12/11/2020

TP without preguise