

BM WHEELPOWER PTE LTD

Ref: GBB4182Y

Ref: SKA3288G

AIG

Not Notation
11 Lm 835,400/r
Recovery After Paint
. 10 days

Date: 7/11/2020
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: PORSCHE 911 CARRERA S 3.8
Chassis No.: WP0ZZZ99ZCS145760
Engine No.: MA103C08068
Year of Make: 2012
Accident Date: 5 November 2020

DATE FOR VEHICLE NO.: SKA3288G

DESCRIPTION	QTY	List Price
REAR BUMPER <i>2305.40</i>	1	\$ <i>R</i> ✓ 2,700.00
REAR BUMPER LOWER COVER - BLACK	1	\$ <i>R/LCP</i> ✓ 380.00
REAR LOWER COVER EXHAUST TIP LH - BLACK	1	\$ <i>Red</i> ✓ 120.00
REAR LOWER COVER EXHAUST TIP RH - BLACK	1	\$ <i>Ln</i> X 120.00
REAR BUMPER TOWING COVER	1	\$ <i>Ln</i> X 60.00
REAR BUMPER LOWER COVER STRIP - BLACK	1	\$ <i>R</i> 100.00 X
REAR BUMPER LH RETAINER	1	\$ <i>Ln</i> 390.00 X
REAR BUMPER RH RETAINER	1	\$ <i>Ln</i> X 390.00
REAR BUMPER HEAT DEFLECTOR UPP CENTER	1	\$ <i>Di</i> 495.00 ✓
REAR BUMPER HEAT DEFLECTOR LOWER CNETER	1	\$ <i>Di</i> 150.00 ✓
REAR BUMPER RH SIDE BRACKET	1	\$ <i>R</i> X 756.00
REAR BUMPER LH SIDE BRACKET	1	\$ <i>R</i> 756.00 X
REAR REINFORCEMENT <i>877.10</i>	1	\$ <i>R</i> ✓ 1,026.00
REAR REINFORCEMENT HEAT DEFLECTOR	1	\$ <i>Red</i> 450.00 ✓
TRUNK LID	1	\$ <i>R</i> X 969.00
TRUNK VENTILATION GRILLE BRACKET	1	\$ <i>R</i> 1,260.00 X
TRUNK VENTILATION TRIM SET - WHITE	1	\$ <i>CM</i> 900.00 ✓
TRUNK LID LOCK	1	\$ <i>R</i> 522.00 X
TRUNK LOWER FAN	1	\$ <i>Ln</i> 468.00 X
TRUNK HINGE LH	1	\$ <i>R</i> 245.00 X
TRUNK HINGE RH	1	\$ <i>R</i> 245.00 X
TRUNK ACTUATOR	1	\$ <i>Ln</i> 220.00 X
REAR SPOILER TOP	1	\$ <i>CM</i> ✓ 925.00

REAR SPOILER BOTTOM	1	\$	CRA ✓	396.00
REAR SPOILER DRIVE UNIT	1	\$	R	4,680.00 X
REAR WINDSCREEN LINING	1	\$	R	750.00 X
REAR HYDRAULIC UNIT	1	\$	R	4,068.00 X
CYLINDER FOR CONVERTIBLE TOP LH	1	\$	R	1,224.00 X
CYLINDER FOR CONVERTIBLE TOP RH	1	\$	R	1,224.00 X
RETAINING FRAME FOR ROLL BAR	1	\$	R	6,120.00 X
TAIL LAMP LH 1560.80	1	\$	CM ✓	2,419.00
TAIL LAMP RH 1560.80	1	\$	O.D (CM)	2,419.00
REAR REFLECTOR LH	1	\$	CM -	103.00
REAR REFLECTOR RH	1	\$	R X	103.00
EXHAUST MANIFOLD LH	1	\$	R B	8,280.00 X
EXHAUST MUFFLER LH 1513.20	1	\$	B	3,600.00 ✓
EXHAUST SILENCER 2678.40	1	\$	Dent 7	3,650.00 ✓
TAIL PIPE LH - BLACK 563.20	1	\$	Net ✓	1,663.00
TAIL PIPE RH - BLACK	1	\$	R X	1,663.00
TAIL PIPE CLAMP	2	\$	Nil	200.00 ✓
RADIATOR TANK	1	\$	R	435.00 X
REAR WINDSCREEN WITH SOFT TOOP with screen 13816	1	\$	Shatter	16,830.00 ✓
Total: \$				73,474.00
LESS 10% \$				(7,347.40)
Parts Total: \$				66,126.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT	1	\$	<i>NN</i>	80.00 X
REAR NUMBER PLATE	1	\$	<i>CM 25m</i>	80.00
COOLANT	1	\$	<i>m</i>	60.00 ✓
WINDSCREEN SEALANT	1	\$	<i>NN X</i>	60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>1300l</i>	<i>800l</i>	1,500.00
TO REMOVE & INSTALL AIRCON COMPONENT INCLUDING CHARGE UP GAS	\$		<i>NN</i>	100.00 X
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$		<i>250l</i>	300.00
TO APPLY ANTI RUST COATING	\$		<i>NN X</i>	150.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$		<i>200l</i>	250.00
TO REMOVE & REPLACE BUMPER SENSORS	\$		✓	60.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$		<i>40l</i>	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$		<i>900l</i>	1,600.00
Total:	\$			70,446.60
7% GST:	\$			4,931.26
Grand Total:	\$			75,377.86

MBM WHEELPOWER PTE LTD



Your Ref: GBB4182Y
Our Ref: SKA3288G

To: AIG

CC

Fax

Date: 18/2/2021
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: PORSCHE 911 CARRERA S 3.8
Chassis No.: WP0ZZZ99ZCS14576Q
Engine No.: MA103C08068
Year of Make: 2012
Accident Date: 5 November 2020

SUPPLEMENTARY FOR VEHICLE NO. : SKA3288G

DESCRIPTION	QTY	List Price	
REAR REINFORCEMENT PANEL <i>5280</i>	1	\$ 6,120.00	<i>By</i> ✓
REAR SPOILER DISC TRIM	1	\$ 1,062.00	<i>CM</i> ✓
EXHAUST SILENCER VACCUM UNIT	1	\$ 430.00	<i>ny</i> ✓
EXHAUST SILENCER VACCUM SHIELD	1	\$ 108.00	<i>nd</i> ✓
EXHAUST CLAMPING SLEEVE	1	\$ 152.00	<i>dis</i> ✓
FRONT RH SEAT BELT - BLACK	1	\$ 1,188.00	<i>Jm</i> ✓
FRONT LH SEAT BELT - BLACK	1	\$ 1,188.00	<i>Jm</i> ✓
AIR CLEANER BOX ASSY <i>1360.60</i>	1	\$ 2,376.00	<i>CM</i> ✓
AIR CLEANER HOSE	1	\$ 260.00	<i>CM</i> ✓
AIR CLEANER BREATHER LINE	1	\$ 648.00	<i>dis</i> ✓
REAR BUMPER "PORSCHE" EMBLEM	1	\$ 367.00	<i>me</i> ✓
REAR BUMPER "911" EMBLEM	1	\$ 259.00	<i>me</i> ✓
REAR BUMPER "CARRERA" EMBLEM	1	\$ 259.00	<i>me</i> ✓
REAR BUMPER "S" EMBLEM	1	\$ 194.00	<i>me</i> ✓
EXHAUST HEAT SHIELD <i>325</i>	1	\$ 585.00	<i>By</i> ✓
ENGINE PROTECTOR PANEL	1	\$ 1,512.00	<i>By</i> ✓
RADIATOR COOLANT HOSE	1	\$ 80.00	<i>nd</i> ✓
WATER PUMP	1	\$ 1,253.00	<i>Jm</i> ✓
Total:	\$	18,041.00	
LESS 10%	\$	(1,804.10)	
Parts Total:	\$	16,236.90	

SPECIAL NETT

TOWING FEE	1	\$	180.00 <i>1800</i>
------------	---	----	--------------------

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE CHASSIS / REINFORCEMENT PANEL	\$	400.00 <i>2500</i>
TO REMOVE SEATS AND LINING TO REPLACE SEAT BELT	\$	250.00 <i>1200</i>
TO REMOVE & REFIT ENGINE / COMPARTMENT TO FACILITATE REPAIR	\$	800.00 <i>5000</i>
Total:	\$	17,866.90
7% GST:	\$	1,250.68
Grand Total:	\$	19,117.58