

228021002
ASS. REC. B. SUN PIN
SUN PIN
Kenny Ong
From (Person):
Estimated Cost:
Special Instruction:
06/11/2020
Date/Time:

REP: CS19017834/Qsd3-1
ASSIGNMENT (Office)
MS16
Bill to:
OP/TP/WS/TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No.: SLP 9803P
Insured: SMP 1391B
at Workshop m/s: Benefit Auto
Tel: 93291373
of 11 kapi Bukit Road 1 # 01-02 Eunus Technolink
Policy No: 29135271ALM
Claim No: 607906

Sum Insured:
Excess:
Make of Veh:
(Client's Record)
D.O.A. 9/10/2019

CA / REV / REP. / REV 24 HRS
Date/Time: 12:35pm @ 9/10/19
Person Contacted: Dunny
H.O.D. Endorsement:
Vehicle IN/OUT

Date/Time	Action/Instruction
	SLP 9803P - NA / A1919001007/hy
	SMP 1391B - NBA / INC19017714/Y
	Disassemble: 10/10/2019
	After repair: 16/10/2019

ASS. REC. BY:

F. ANN

REF:

MS16

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP 9803 P

at Workshop m/s

BENEFIT Auto-11

of

11 Kaili Bukit Road 1 #01-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X
N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP 9803 P

Yr Regn:

23/06/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3 Sedan

c.c

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

51299 km

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0154500

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60/R16

R:

205/60/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front and Rear sure - (Bund) Yokohama

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/10/19

D.O.I.

9/10/19

Survey held at

BENEFIT Auto-11

Des. of Damages (Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5-6K * SLP 9803 P NON

Range → 4.5 → 6.5K Estimate (PRS)

repair Days → 6 days case #

MV - 59200

PV - 43171

NV - 16000

18/10/2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

3)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

120

Transportation:

S + RS \$

Prints

Others

TOTAL

131

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wash and

Report Format:

PRE.

Lump Sum / 121