

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Apr 2021

Preliminary Advice

Insured Vehicle No	: SGQ3901H	Accident Date	: 04/11/2020
TP Vehicle No	: SLS7973D	Assignment Date	: 10/11/2020
Make	: MAZDA 2	Est. Duration of Repair	: 2
Date of Inspection	: 05/04/2021		
Inspection At	: TRANS EUOKARS PTE LTD (UBI) 5 UBI CLOSE SINGAPORE 408605		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,786.20
Revised Amount	:S\$	1,576.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,576.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey WP