

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Not Authorised

1/1/2020

Penalty After Paint

6 days

Date: 9th Nov 2020

Quotation: SLS 64545

Honda Civic

S\$

|                                          |          |          |   |
|------------------------------------------|----------|----------|---|
| 1 Pc. Rear RH fender                     | R        | 1,138.50 | X |
| 1 Pc. Rear windscreen moulding           | nn       | 190.10   | X |
| 1 Pc. Rear bumper                        | R        | 696.30   | X |
| 1 Pc. Rear bumper side retainer (RH)     | nn       | 34.90    | X |
| 1 Pc. Rear RH door                       | R        | 1,095.20 | ✓ |
| 1 Pc. Rear RH door inner rubber          | nn       | 193.80   | X |
| 1 Pc. Rear RH door protector w/moulding  | nn       | 187.50   | ✓ |
| 1 Pc. Rear RH door glass outer moulding  | nn       | 180.60   | X |
| 1 Pc. Rear RH door outer handle          | nn/nn    | 219.60   | ✓ |
| 1 Pc. Front RH door                      | R        | 1,226.10 | ✓ |
| 1 Pc. Front RH door inner rubber         | nn       | 196.40   | X |
| 1 Pc. Front RH door protector w/moulding | nn       | 219.50   | ✓ |
| 1 Pc. Front RH door glass outer moulding | SVC      | 188.20   | X |
| 1 Pc. Front RH door outer handle         | nn       | 238.10   | ✓ |
| 1 Pc. Front RH door side mirror assy.    | CM       | 986.30   | ✓ |
| 1 Pc. Front RH door glass inner seal     | nn       | 93.60    | X |
| 1 Pc. Rear RH door glass inner seal      | nn       | 88.10    | X |
| 1 Pc. Front RH fender                    | R        | 560.90   | X |
| 1 Pc. Front RH headlamp assy.            | CM       | 1,078.10 | ✓ |
| 1 Pc. Front bumper                       | R        | 713.50   | X |
| 1 Pc. Front bumper side retainer (RH)    | nn       | 36.40    | X |
|                                          |          | 9,561.70 |   |
|                                          | Less 20% | 1,912.34 |   |
|                                          | C/fd     | 7,649.36 |   |

# NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194  
SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

S\$

b/fd

7,649.36

## Nett Items:-

|                                    |             |
|------------------------------------|-------------|
| 2 Sets RH door frame black sticker | nn 180.00 ✓ |
| 2 Sets RH tyre RIMS                | nn 840.00 4 |
| 1 Pc. Rear windscreen sealant      | nn 120.00 X |
| 1 Pc. Rear RH fender sealant       | nn 100.00 1 |

## Labour Charges:-

|                                                             |                  |
|-------------------------------------------------------------|------------------|
| ① To focus headlight & check wiring                         | 60.00 2ol        |
| ② Computerised wheel alignment                              | nn 100.00 X      |
| ③ Rustproofing                                              | 120.00 6ol       |
| ④ Remove & refix rear windscreen                            | nn 160.00 X      |
| ⑤ Remove & refix cushions, carpets, side cover & upholstery | } nn 320.00 X    |
| ⑥ Remove & transfer both RH door inner items                |                  |
|                                                             | 200.00 12ol      |
| ⑦ Remove & instal reverse sensor                            | nn 100.00 X      |
| ⑧ Remove & refix both tyres & wheel balancing               | } 90.00 2ol      |
| ⑨ Panel beating                                             |                  |
| ⑩ Spray painting                                            | 1,600.00 7ol     |
|                                                             | 2,000.00 12ol    |
| <b>Total:</b>                                               | <b>13,639.36</b> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: