

ASS. REC. BY:

REF: C72 / 200123001KV

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

09/25

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GB3 8298X

Yr Regn:

04, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mr Vito 111 Cdc.c

2143

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

259819

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDF 639805 23559597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

GT 215/65R16

R: Maxmike

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

P

mm

L/Bal.

9

mm

L/Bal.

P

mm

D.O.A.

2/11/20

D.O.I.

18/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ Wksp will email documents over.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 16/12/20-Typist

Report Format: Merimen

Lump Sum / H.B.T. (\$) 3100

Days Of Repair: 5

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + R.S. SI

Fees

Others

TOTAL

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MERCEDES BENZ VITO 111 CDI

Engine/Chassis No.: WDF63960523559597


Date of accident:

Damaged area: O/S

Date: 18/11/2020

Claim Type: TP

VRN: GBB8298X



Not Authorized
U/Sing B
Put away After Paint

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear fender o/s	1	\$ 1,276.00	\$ 1,276.00
2	Rear fender inner cowling o/s	1	\$ 185.00	\$ 185.00
3	Rear fender outer moulding o/s	1	\$ 476.00	\$ 476.00
4	Sliding door o/s	1	\$ 1,904.00	\$ 1,904.00
5	Sliding door inner trim board o/s	1	\$ 683.00	\$ 683.00
6	Sliding door top roller hinge o/s	1	\$ 102.00	\$ 102.00
7	Sliding door lower roller hinge o/s	1	\$ 102.00	\$ 102.00
8	Sliding door stopper o/s	2	\$ 55.00	\$ 110.00
9	Sliding door outer handle o/s	1	\$ 192.00	\$ 192.00
10	Sliding door lock o/s	1	\$ 433.00	\$ 433.00
11	Sliding door outer moulding o/s	1	\$ 497.00	\$ 497.00
Subtotal				\$ 5,960.00
List discount				10.00%
Total				\$ 5,364.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries	1	\$ 50.00	\$ 50.00
2	Rear sliding door inner trim board clips o/s	8	\$ 6.50	\$ 52.00
3	Rear fender inner cowling clips o/s	8	\$ 6.50	\$ 52.00
Total				\$ 154.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00

700L

Repair Estimate

2	To disconnect doors wire harness of electrical component to facilitate repairs, reconnect and check functions of power windows.	0.25	\$	50.00
3	To remove and refit o/s sliding door components for replacement, check alignment.	0.5	\$	100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	4	\$	800.00
5	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	2,050.00
Estimate Grand Total			\$	7,568.00

20%
60%
400%
60%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: