

File No : SH/202
Date : 10-November-2020

Perdeep Kumar S/O Atma Singh
58 Cowdray Avenue
Singapore 558059

Not Authorised
11/Nov @ 3100h
Repairing B&P

Qidari

Estimated cost of repair for vehicle no : SMD3532L Hyundai Elantra
Accident involving vehicle no: SMD3532L & SLF25E on 06.11.2020

Description	Quantity	Cost Price
Rear boot	1	\$ <i>B</i> 1,782.00 ✓
Rear boot inner lock	1	\$ <i>R</i> 162.00 X
Rear boot badge "elantra"	1	\$ <i>m</i> 38.00 ✓
Rear boot badge "elite"	1	\$ <i>m</i> 48.00 —
RH Rear boot hinge	1	\$ <i>R</i> 94.30 X
LH Rear boot hinge	1	\$ <i>R</i> 94.30 X
Rear end panel	1	\$ <i>R</i> 454.60 X
Rear bumper	1	\$ <i>Bulcom</i> 459.40 ✓
Rear bumper clips (1 set)	1	\$ <i>m</i> 28.00 ✓
Rear bumper reinforcement	1	\$ <i>B</i> 480.00 ✓
RH Rear bumper retainer	1	\$ <i>Diy</i> 44.30 ✓
LH Rear bumper retainer	1	\$ <i>Diy</i> 44.30 ✓
Rear bumper centre lower moulding	1	\$ <i>Diy</i> 250.10 ✓
LH Rear bumper lower dust cover	1	\$ <i>CM</i> 47.20 ✓
RH Rear bumper reflector	1	\$ <i>CM</i> 40.80 ✓
		\$ 4,067.30
	less 20%	\$ 813.46
		\$ 3,253.84
Rear parking sensors (1 set)	1	\$ <i>net</i> 220.00 <i>2005h</i>
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and tailgate alignment		\$ 550.00 <i>45d</i>
To apply anti-corrosion Tuff-Kote on rewelded seams		\$ 100.00 <i>30d</i>
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material		\$ 650.00 <i>60d</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality		\$ 35.00 <i>20d</i>
		\$ 4,808.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

T/Party: AIG Asia Pacific Insurance Pte. Ltd.