

ASS. REC. BY:

REF:

AIG/ 20012308/kb

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDN 8988 B

Yr Regn:

10, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Volkswagen

Sportsvan

75i 1395

Colour

N. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

81357

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888 AU 7 GW 529537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

31/8/20

D.O.I.

25/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/12 11:20 AM 812001

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
 Email: yeeautopte ltd@gmail.com  
 Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
 78 Shenton Way  
 #07-16  
 Singapore 079120

Estimate No: **ES2000105**  
 Date: 25 Nov 2020  
 Policy No:  
 Veh Reg No: **SDN8988B**  
 Make/Model: VOLKSWAGEN SPORTSVAN 1.4 AT AM13HZ CL  
 Chassis No: WVWZZZAUZGW529557  
 Engine No: CZC418573  
 Reg. Date: 14/10/2016

ATTN: Motor Claim Department

Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 31/08/2020  
 TP Veh Reg No: SKF2868M

*Not Authorised*  
*11/08/2020*  
*Running After Rain*  
*2 days*

## Estimate Repair Cost to Vehicle No :SDN8988B

| Description                                                          | U/Price  | Quantity | List Price<br>SS | Amount<br>SS |
|----------------------------------------------------------------------|----------|----------|------------------|--------------|
| <b>Spare Parts</b>                                                   |          |          |                  |              |
| 1 REAR BUMPER                                                        | 1,450.50 | 1 PC     | 1,450.50         | ✓            |
| 2 REAR BUMPER SIDE RETAINER - LH                                     | 65.20    | 1 PC     | 65.20            | X            |
| 3 REAR BUMPER SIDE RETAINER - RH                                     | 65.20    | 1 PC     | 65.20            | X            |
| 4 REAR BUMPER REFLECTOR - RH                                         | 195.15   | 1 PC     | 195.15           | X            |
| 5 REAR BUMPER LOWER PAD                                              | 285.10   | 1 PC     | 285.10           | X            |
| 6 REAR BUMPER CLIPS                                                  | 50.00    | 1 SET    | 50.00            | ✓            |
| 7 REAR BUMPER REINFORCEMENT                                          | 620.00   | 1 PC     | 620.00           | X            |
| 8 REAR BUMPER TOWING COVER                                           | 60.00    | 1 PC     | 60.00            | X            |
| 9 TAIL LAMP RH                                                       | 585.50   | 1 PC     | 585.50           | X            |
|                                                                      |          |          | 3,376.65         | 3,376.65     |
| <b>Labour</b>                                                        |          |          |                  |              |
| 10 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. | 600.00   | 1 JOB    | 600.00           | 200/         |
| 11 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.     | 600.00   | 1 JOB    | 600.00           | 220/         |
| 12 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.              | 200.00   | 1 JOB    | 200.00           | X            |
| 13 TO CHECK WIRING FUNCTIONS.                                        | 80.00    | 1 JOB    | 80.00            | 15/          |
|                                                                      |          |          | 1,480.00         | 1,480.00     |

Total S\$ 4,856.65

Add GST @ 7% 339.97

Total Amount Payable S\$ 5,196.62

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED NINETY SIX AND CENTS SIXTY TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE