

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31498

Vehicle Insured : GBG 2361 J
Accident Date : 29-Oct-2020

Not Authorised

Date : 02-Nov-2020

Our Ref : 020520 (CHINA) / QUEK

Recovery B4 paint

PAGE : 1

CHUA HUAT HWEE (MR)
Singapore

5 days

ESTIMATED COST OF REPAIR FOR HYUNDAI AD AVANTE 1.6 GLS (A)(2019) SMH5708M
=====

2 pcs rear number plate lamp	@ S\$ 28.00	<i>Sm</i> 56.00	X
1 pc rear bumper - top		<i>Bu</i> 459.40	✓
1 pc rear bumper - lower		<i>CM</i> 353.30	✓
2 pcs rear bumper lower lamp(LH/RH)	@ S\$201.50	<i>CM</i> 403.00	✓
10 pcs rear bumper clips	@ S\$ 2.00	<i>Sm</i> 20.00	✓
1 pc rear bumper reinforcement		294.80	?
2 pcs rear bumper reinforcement bracket (LH/RH)	@ S\$ 78.60	157.20	?
3 pcs rear bumper lower bracket stay	@ S\$ 5.00	15.00	?
2 pcs rear bumper upper bracket stay	@ S\$ 5.00	10.00	?
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 29.40	<i>MSD</i> 58.80	✓
1 pc rear bumper side lower undercover -LH		<i>Sm</i> 37.20	X
1 pc rear bumper side lower undercover - RH		<i>Sm</i> 20.00	X
1 pc rear bumper lower lamp wireharness		<i>Sm</i> 122.60	X
1 pc bootlid		<i>Ry</i> 1,782.40	✓
1 pc bootlid lock		<i>ms</i> 116.20	✓
1 pc bootlid lock catch		<i>R</i> 15.00	X
1 pc bootlid logo <i>Pr?</i>		<i>ms</i> 196.20	✓
1 pc bootlid 'AVANTE' emblem		<i>ms</i> 31.20	✓
1 pc bootlid weatherstrip		<i>ms</i> 92.50	?
2 pcs bootlid lamp (LH/RH) <i>old cm</i>	@ S\$284.90	<i>Sm</i> 569.80	X
1 pc bootlid inner trimlining		<i>Sm</i> 146.80	X
8 pcs bootlid inner trimlining clips	@ S\$ 2.00	<i>ms</i> 16.00	X
1 pc bootlid reverse camera		826.10	?
1 pc rear end panel		<i>Ry</i> 454.60	✓
1 pc rear end panel top garnish		59.80	?

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBG 2361 J
Our Ref : 020520

Page : 2
No. : 31498

2 pcs taillamp assy (LH/RH)

n/s Tax @ S\$435.10

870.20

7,184.10

Less 20% : -1,436.82

5,747.28

1 pc rear number plate

1 pc reverse sensor assy

sn 40.00 *sn X*
220.00 *sn ?*

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

600k
800.00

To remove and refit reverse sensor
assy.

60.00 *50k*

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

120.00 *60k*

80.00 *60k*

50.00 *20k*

To apply undersealing

To focus taillamps. To check rear
wiring and lighting operation.

680.00 *600k*

To putty and respray on affected
portions.

Total : S\$ 7,797.28

=====

Singapore Dollars Seven Thousand Seven Hundred
and Ninety Seven and Cents Twenty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.