

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20010431/R1TF3E2-1

Date: 20/11/2020

REFERENCE

Insured/Claimant:	SOH BENSON	Policy No:	2100506984
Date of Loss:	27/09/2020	Nature of Claim:	OD
		Claim No:	6189821337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM9650D	Engine No:	3A92UDT3433
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH004738
Reg. Date:	19/04/2017 (Man. Year: 2016)	Odometer:	82400 km
Colour:	White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,600.00	8,600.00	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,611.00	8,611.00	0.00	0.00
- Excess (\$\$)	0.00	300.00	-300.00	
(\$\$)	8,611.00	8,311.00	300.00	3.48
+ GST 0.00/7.00% (\$\$)	0.00	581.77	-581.77	
Nett Amount (\$\$)	8,611.00	8,892.77	-281.77	-3.27

INSPECTION

Date of Assignment:	21/10/2020 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	29/09/2020 Inspected At:	SME Motor Pte Ltd (Kaki Bukit)
		1 Kaki Bukit Ave 6 #02-15, AutoBay @
		Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COST OF REPAIR (TENDER)		8,600.00 F	*8,600.00 F
				Total Parts (S\$)	8,600.00	8,600.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >