

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 13 Apr 2021

## **Preliminary Advice**

Insured Vehicle No : GBG9650D  
TP Vehicle No : GBF8941B  
Make : TOYOTA HIACE  
Date of Inspection : 11/11/2020  
Inspection At : ACE AUTOLUTION PTE LTD (KAKI BUKIT)  
13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE  
SINGAPORE 417807  
Accident Date : 05/11/2020  
Assignment Date : 10/11/2020  
Est. Duration of Repair : 5

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,390.11
Revised Amount	:S\$	4,577.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,577.00
Lump Sum Repair	:S\$	3,600.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp