



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2011-169
DATE : 10-Nov-2020
POLICY NO. : MSIG A300194271MKC
VEHICLE REG. NO. : YN7030Y
VEHICLE MAKE : MITSUBISHI CANTER FEB21ER3SDEB

TO Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street, #04-#05 IOB Building, Singapore 049711
Tel: 6347 6100
Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear License Plate Lamp <i>CR</i>	1	\$ 200.00	\$ 200.00
2	Rear License Bracket <i>4</i>	1	\$ 100.00	\$ 100.00
3	Rear Tail Lamp RH <i>CR</i>	1	\$ 300.00	\$ 300.00
Total Spare Parts				\$ 600.00
SPECIAL NETT				
4	Rear License Plate <i>4</i>	1	\$ 40.00	\$ 40.00
5	Tailgate Metal Frame RH <i>X SUC</i>	1	\$ 200.00	\$ 150.00
6	Rear Reinforcement Top Bar <i>4</i>	1	\$ 250.00	\$ 250.00
7	Rear Reinforcement Top Bar Bracket RH <i>X SUC</i>	1	\$ 100.00	\$ 100.00
8	Rear Reinforcement Bolt & Lock Nut <i>X SUC</i>	10	\$ 6.00	\$ 60.00
9	Rear Reinforcement Lower Bar Assy (14FT) <i>X SUC</i>	1	\$ 600.00	\$ 600.00
Total Special Nett				\$ 1,200.00
LABOUR				
10	Spray Painting Whole Rear	1	\$ 600.00	\$ 600.00
11	Remove, Refit and Repair Affected Accident Parts	1	\$ 600.00	\$ 600.00
12	Anti-Rust Tuff Coat	1	\$ 80.00	\$ 80.00
13	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,310.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Amount Before Excess \$ 3,110.00
Add GST @ 7% 217.70
Total Amount Payable \$ 3,327.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 900w68
2 days

4/5
30/11/2020 @ 1440

Resy after repair 2 days

450
185
470
1105
200
884
45900

Rep-Formet: