

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
After
Respray ~~the~~ paint
B4
6459 86950h

Date : 10/11/2020

QUOTATION -THIRD PARTY CLAIM

INDIA INTERNATIONAL INSURANCE PTE LTD

WDD 2050422R119099

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SML 1146 L
Model : MERCEDES C 200
Insured Ins: AIG ASIA PACIFIC

Accident on : 09/11/2020

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SHD 4233 C		
1	BOOTLID	REPAIR	
1	BOOTLID CENTER LOGO 80	\$ 140.00	—
1	REAR FENDER RH	REPAIR	
1	FRONT RH SEAT BELT 725	\$ 1,125.00	—
1	SEAT BELT ECU 1850	\$ 3,250.00	—
1	SEAT BELT BUCKLE RH	\$ 580.00	X
1	TAILALMP LH 748	\$ 1,480.00	X
1	TAILLAMP LOWER BRACKET LH	\$ 385.00	X
1	REAR BUMPER SIDE SENSOR LH 0245	\$ 380.00	—
1	REAR BUMPER CENTER SENSOR LH	\$ 380.00	X
1	REAR DIFFUSER SENSOR LH	\$ 380.00	X
1	END PANEL	\$ 850.00	X
1	END PANEL TOP GARNISH	\$ 480.00	X
1	REAR BUMPER SENSOR CABLE	\$ 1,125.00	X
3	REAR BUMPER SENSOR BRACKETS	\$ 504.00	X
1	REAR BUMPER LH SIDE BRACKETS	\$ 480.00	X
1	REAR BUMPER SPONGE	\$ 450.00	X
1	REAR BUMPER REINFORCEMENT 646	\$ 780.00	X
1	REAR EXHAUST	\$ 2,240.00	X 3505n
1	REAR EXHAUST MOUNTING	\$ 385.00	X
	TOTAL :	\$ 15,394.00	
	LESS 10%	\$ 13,854.60	
	S/NETT		
1	REAR BUMPER (AMG) (After market) 28505n CMA	\$ 4,800.00	—
8	REAR BUMPER CLIPS	\$ 450.00	— 805n
15	REAR BUMPER RIVET	\$ 45.00	—
1	REAR BUMPER CENTER DIFFUSER 18005n	\$ 3,500.00	—
1	REAR BUMPER LH SIDE LOWER SPOILER	\$ 500.00	X
2	REAR BUMPER SIDE FINS	\$ 800.00	X
2	REAR EXHAUST CHROME END LH	\$ 1,600.00	X
	TOTAL S/N PARTS	\$ 11,695.00	
	TOTAL PARTS :	\$ 25,549.60	

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 25,549.60	
	Labour charges to do cutting , welding , remove refix, replace rear accident affected area	\$ 1,400.00	4000
	To replace rear exhaust <i>nn</i>	\$ 200.00	X
	To replace rear sensor and cable assy <i>nn</i>	\$ 250.00	X
	To check wiring system.	\$ 150.00	200
	To replace seat belt and ECU	\$ 250.00	150
	To remove refix, replace garnish, side trim, car seat, upholstery etc	\$ <i>nn</i> 350.00	X
	To do anti rust	\$ <i>nn</i> 100.00	X
	To do sealant, seal gap, waterproofing on cutting wedling accident area	\$ <i>nn</i> 200.00	X
	To delete reset fault code, programming ecu after repair	\$ 500.00	2500
	To do spray painting on accident affected area	\$ 1,400.00	5000
	TOTAL LABOUR :	\$ 4,800.00	
	TOTLA PARTS & LABOUR :	\$ 30,349.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: