

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
After
Recovery By paint
By
6/11/20

Date : 10/11/2020

QUOTATION -THIRD PARTY CLAIM

INDIA INTERNATIONAL INSURANCE PTE LTD

Attn: Motor Claim Department, Officer In Charge

Accident on : 09/11/2020

Claim : Third Party Claim
Veh. No : SML 1146 L
Model : MERCEDES C 200
Insured Ins: AIG ASIA PACIFIC

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SHD 4233 C		
		REPAIR	
1	BOOTLID	\$ 140.00	✓
1	BOOTLID CENTER LOGO	REPAIR	
1	REAR FENDER RH	\$ 1,125.00	✓
1	FRONT RH SEAT BELT	\$ 3,250.00	✓
1	SEAT BELT ECU	\$ 580.00	X
1	SEAT BELT BUCKLE RH	\$ 1,480.00	?
1	TAILALMP LH	\$ 385.00	?
1	TAILLAMP LOWER BRACKET LH	\$ 380.00	✓
1	REAR BUMPER SIDE SENSOR LH	\$ 380.00	X
1	REAR BUMPER CENTER SENSOR LH	\$ 380.00	X
1	REAR DIFFUSER SENSOR LH	\$ 850.00	X
1	END PANEL	\$ 480.00	X
1	END PANEL TOP GARNISH	\$ 1,125.00	?
1	REAR BUMPER SENSOR CABLE	\$ 504.00	?
3	REAR BUMPER SENSOR BRACKETS	\$ 480.00	?
1	REAR BUMPER LH SIDE BRACKETS	\$ 450.00	?
1	REAR BUMPER SPONGE	\$ 780.00	?
1	REAR BUMPER REINFORCEMENT	\$ 2,240.00	?
1	REAR EXHAUST	\$ 385.00	?
1	REAR EXHAUST MOUNTING		
	TOTAL :	\$ 15,394.00	
	LESS 10%	\$ 13,854.60	
	S/NETT		
1	REAR BUMPER (AMG)	\$ 4,800.00	✓
8	REAR BUMPER CLIPS	\$ 450.00	✓
15	REAR BUMPER RIVET	\$ 45.00	✓
1	REAR BUMPER CENTER DIFFUSER	\$ 3,500.00	✓
1	REAR BUMPER LH SIDE LOWER SPOILER	\$ 500.00	X
2	REAR BUMPER SIDE FINS	\$ 800.00	?
2	REAR EXHAUST CHROME END LH	\$ 1,600.00	?
	TOTAL S/N PARTS	\$ 11,695.00	
	TOTAL PARTS :	\$ 25,549.60	

AUTOEXCEL ENGINEERING PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-15
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64531608

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 25,549.60	
	Labour charges to do cutting , welding , remove refix, replace rear accident affected area	\$ 1,400.00	4000
	To replace rear exhaust	\$ 200.00	?
	To replace rear sensor and cable assy	\$ 250.00	?
	To check wiring system.	\$ 150.00	200
	To replace seat belt and ECU	\$ 250.00	1500
	To remove refix, replace garnish, side trim, car seat, upholstery etc	\$ 350.00	X
	To do anti rust	\$ 100.00	X
	To do sealant, seal gap, waterproofing on cutting welding accident area	\$ 200.00	X
	To delete reset fault code, programming ecu after repair	\$ 500.00	2500
	To do spray painting on accident affected area	\$ 1,400.00	5000
	TOTAL LABOUR :	\$ 4,800.00	
	TOTAL PARTS & LABOUR :	\$ 30,349.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: