



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 1238S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER	TO REPAIR SEE LABOUR	920.90	-
1	FRONT DOOR ASSEMBLY	DENTED	2,215.70	1,863.00
1	FRONT DOOR WEATHERSTRIP	NECESSARY	210.00	210.00
1	FRONT DOOR OUTER CARRIER	SERVICEABLE	180.00	-
1	FRONT DOOR INNER LOCK	SERVICEABLE	245.00	-
1	FRONT DOOR WINDOW REGULATOR	SERVICEABLE	480.00	-
1	FRONT DOOR WINDOW REGULATOR MOTOR	SERVICEABLE	420.00	-
1	FRONT DOOR WINDOW GLASS CHANNEL RUBBER	NECESSARY	170.00	170.00
1	FRONT DOOR WINDOW GLASS CHANNEL BRACKET	NECESSARY	85.00	85.00
	LESS 10% DISCOUNT		-492.66	-232.80
			4,433.94	2,095.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	WHEEL RIM ASSY (SPORT) (SN)	SCRATCHED	450.00	450.00
1	ROCKER PANEL GARNISH (SN)	TO REPAIR SEE LABOUR	550.00	-
10	ROCKER PANEL GARNISH CLIPS (SN)	SERVICEABLE	80.00	-
			1,080.00	450.00
	<b><u>LABOUR</u></b>			
	TO TUFF COAT AFFECTED AREAS.		180.00	40.00
	TO REMOVE AND TRANSFER FRONT DOOR MECHANISM.		180.00	60.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	600.00
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	180.00	-
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR DOOR CENTER PILLAR (INNER), FRONT DOOR PILLAR, REAR FENDER, ROCKER PANEL AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER AND ROCKER PANEL GARNISH.		1,800.00	400.00
	TO RESET ELECTRICAL MODULE SYSTEM.	NOT NECESSARY	300.00	-
			4,240.00	1,100.00
	<b>GRAND TOTAL</b>		<b>9,753.94</b>	<b>3,645.20</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,900.00</b>
---	--	--	-----------------

Report Ref No. CS3/AIG20009128/Qvf3e2-1

**OI SUN PIN**

**Asst. Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.