

Section A - Accident Details

Registration Number	SHC4769D
Case Reference Number	TAX/11/20/2013
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN POH HOCK
Type of Accident	Head to Rear
Accident Date and Time	4/11/2020 3:20 PM
Accident Reported Date and Time	7/11/2020 10:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108744
Special Instruction to ARC, if any	FRONT AND REAR PORTION / CHINA TAIPING - LKK
Prepared Date and Time	9/11/2020 11:15 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$1,300.00
Total Spray Cost	\$0.00	\$1,980.00
Total Spare Part Cost	\$14,577.83	\$7,133.29
Total Other Cost	\$0.00	\$500.00
TOTAL COST	\$14,577.83	\$10,913.29
Lump Sum Total	\$21,950.00	\$10,900.00 (L/S)
Number of Repair Days	10.0	9.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	13/11/2020 12:44 PM	13/11/2020 12:00 PM
Signature		
Remarks	Total number of repair days = 9 DAYS SUP = 3 DAYS	L/S, After paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2012-0002	Invoice Number	
Quotation Date	01.12.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$676.00	\$600.00
TO REPAIR RH REAR WHEEL HOUSE	\$200.00	\$100.00
TO REPAIR REAR CHASSIS RH	\$400.00	\$200.00
TO REPAIR REAR SPARE TYRE PANEL	\$350.00	\$200.00
Total Labour	\$1,964.00	\$1,300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$80.00
TO RESPRAY REAR PANEL	\$180.00	\$200.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$100.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$250.00	\$200.00
TO RESPRAY REAR CHASSIS RH	\$200.00	\$100.00
TO RESPRAY RH REAR WHEEL HOUSE	\$200.00	\$200.00
Total Spray Painting & Panel Beating	\$3,998.00	\$1,980.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$100.00
TO REMOVE AND REFIX TAILGATE GLASS	\$120.00	\$100.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 01/12/2020

User ID PohSuan

TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO ALIGN CHASSIS	\$350.00	\$150.00
Total Other Costs	\$1,430.00	\$500.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	CR4
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	NPC
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	SVC
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	SVC
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	SVC
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	SVC
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	SVC
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	SVC
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	CR4
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	CR4
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	CR4
		52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace	MIS
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	CR4
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	SVC
		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace	NPC
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	SVC
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	SVC
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	SVC
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	SVC
		51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Check	SVC
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	CR4
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	NPC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	NPC
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	BT
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.66	Replace	Replace	CR4
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	short
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	BR
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	BR
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	SVC
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check	SVC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	SVC
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check	SVC
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	CR4
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 01/12/2020

User ID PohSuan

51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Check	X	SUC
58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace		DD
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace		CRU
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace		CRU
	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace		Nec
64993-47020	BOX, DECK FLOOR, RR	1.00	\$649.70	25.00	\$487.28	Replace	Replace		CRU
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	X	SUC
	BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Check	X	SUC
17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Not Given	X	SUC
17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Not Given	X	SUC
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X	SUC
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X	SUC
67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace		PD
75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace		Nec
75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace		Nec
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace		Nec
64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$721.30	25.00	\$540.98	Replace	Replace		Nec
	SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace		Nec
82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Check	X	SUC
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X	SUC
68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X	SUC
68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X	SUC
69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace		Jam
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X	SUC
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X	SUC
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace		CRU
67938-47031C0	TAILGATE TRIM, LH	0.00	\$85.90	0.00	\$0.00	Replace	Check		SUC
67937-47031C0	TAILGATE TRIM, RH	0.00	\$88.30	0.00	\$0.00	Replace	Check	X	SUC
67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Check	X	SUC
64790-47030C0	TAILGATE TRIM, UPPER	0.00	\$49.60	0.00	\$0.00	Replace	Not Given	X	SUC
67750-47071C0	TAILGATE, BAORD ASSY	1.00	\$246.90	25.00	\$185.18	Replace	Replace		CRU
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace		CRA
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace		Nec
75442-47030	NAME PLATE (PRUIS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace		Nec
75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace		Nec
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X	SUC
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X	SUC
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace		Nec
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace		Nec
81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X	SUC
76085-47910	SPOILER REAR	1.00	\$953.70	100.00	\$0.00	Replace	Repair		
67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair		

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/12/2020

User ID : PohSuan

69050-47080	DOOR LOCK RR/RH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X	SUC
68770-52031	DOOR HINGE LOWER RR/RH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	SUC
68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X	SUC
68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	SUC
61604-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10	Replace	Replace		DB
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace		Nec
	STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace		Nec
65637-47021	FENDER LINE RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X	SUC
81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace		CR4
52562-47010	TAIL LAMP BRACKET, RH	1.00	\$30.70	25.00	\$23.03	Replace	Replace		BR
61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X	SUC
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	SUC
	STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	SUC
65638-47021	FENDER LINER R/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X	SUC
81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X	SUC
Total			\$21,094.61		\$7,220.12				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
52611-47080			BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace	CR4
52021-47023			BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace	BT
57014-47030			ARM SUB-ASSY,FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace	BT
76087-47020			BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	CR4
			BATTERY	1.00	\$278.00	0.00	\$278.00	Replace	Replace	CR4
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	CR4
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	SCR
64730-47031B2			PANEL ASSY, DECK RH	1.00	\$307.00	25.00	\$230.25	Replace	Replace	DRF
58490-47140B0			BOARD ASSY, RR RH	1.00	\$379.20	25.00	\$284.40	Replace	Replace	ERA
			SPARE TYPE INSULATOR SHEET	3.00	\$15.00	0.00	\$45.00	Replace	Replace	Nec
64778-47050			PROTECTOR, SPARE	1.00	\$143.70	25.00	\$107.78	Replace	Replace	CRU
51931-47020			CARRIER, SPARE	1.00	\$19.70	25.00	\$14.78	Replace	Replace	BT
Total					2,115.30		1,696.49			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8916.61 /

- 202

1133.29 /

+ 1300.00 /

+ 2480.00 /

10913.29 /

45 \$10,900 /

9 days